3-27-89
7:00

0015

RVS

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340



# inspection report

Permit No. INA/015/002

Inspection Date MARCH 7, 1989

Permittee/Operator Name WESTERN STATES MINERALS CORP.

Business Address 4975 VAN GORDON ST.

City WHEAT RIDGE State CO Zip 80033

Mine J. B. KING ☐ Surface ☒ Underground ☐ Other

County EMERY State UT

Company Official(s) NONE

State Official(s) BILL WAKEMACK

Time of inspection 12 30 ☐ a.m. ☒ p.m. to 2 00 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete

Date of last inspection 2/1/89 Weather conditions OVERCAST & COOL

Acreage 480 ☒ Permitted 30 ☒ Disturbed 30 ☒ Regraded 30 ☒ Seeded 30 ☒ Bonded

Enforcement Action NONE

## COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

| | YES | NO | N/A | COMMENTS |
|---|---|---|---|---|
| 1. Permits | ☐ | ☐ | ☐ | ☐ |
| 2. Signs and markers | ☐ | ☐ | ☐ | ☐ |
| 3. Topsoil | ☐ | ☐ | ☐ | ☐ |
| 4. Hydrologic balance | | | | |
| a Stream channel diversions | ☐ | ☐ | ☐ | ☐ |
| b Diversions | ☐ | ☐ | ☐ | ☐ |
| c Sediment ponds and impoundments | ☐ | ☐ | ☐ | ☐ |
| d Other sediment control measures | ☒ | ☐ | ☐ | ☒ |
| e Surface and groundwater monitoring | ☐ | ☐ | ☐ | ☐ |
| f Effluent limitations | ☐ | ☐ | ☐ | ☐ |
| 5. Explosives | ☐ | ☐ | ☐ | ☐ |
| 6. Development waste and spoil disposal | ☐ | ☐ | ☐ | ☐ |
| 7. Coal processing waste | ☐ | ☐ | ☐ | ☐ |
| 8. Noncoal waste | ☐ | ☐ | ☐ | ☐ |
| 9. Protection of fish, wildlife, and related environmental values | ☐ | ☐ | ☐ | ☐ |
| 10. Slides and other damage | ☐ | ☐ | ☐ | ☐ |
| 11. Contemporaneous reclamation | ☐ | ☐ | ☐ | ☐ |
| 12. Backfilling and grading | ☐ | ☐ | ☐ | ☐ |
| 13. Revegetation | ☐ | ☐ | ☐ | ☐ |
| 14. Subsidence control | ☒ | ☐ | ☐ | ☒ |
| 15. Cessation of operations | ☐ | ☐ | ☐ | ☐ |
| 16. Roads | | | | |
| — Construction | ☐ | ☐ | ☐ | ☐ |
| — Drainage controls | ☐ | ☐ | ☐ | ☐ |
| — Surfacing | ☐ | ☐ | ☐ | ☐ |
| — Maintenance | ☐ | ☐ | ☐ | ☐ |
| 17. Other transportation facilities | ☐ | ☐ | ☐ | ☐ |
| 18. Support facilities and utility installations | ☒ | ☐ | ☐ | ☒ |

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining



## INSPECTION REPORT COMMENTS

Permit No. INA/015/002

Inspection Date 3/7/89

Please number comments to correspond with topics on previous page.

GENERAL: FOR THE MOST PART, SNOW WAS ABSENT FROM THE MINE SITE. GROUND CONDITIONS WERE WET ESPECIALLY ALONG THE CHANNEL BOTTOMS & NORTH FACING SLOPES.

4d. OTHER SEDIMENT CONTROLS: THE SILT FENCES, BERMS & CONTOURS WERE INTACT, HOWEVER, REPAIRS TO THE CATTLE IMPACTS SHOULD BE INITIATED DURING THE UPCOMING MONTHS AS THE GROUND THAWS. (SEE INSPECTION REPORT 2/1/89).

14. SUBSIDENCE CONTROL: SOME SETTLING ALONG THE SUBSIDENCE CRACKS WAS NOTED. THE AREAS HAD BEEN FILLED WITH SAND LAST FALL ('88).

18. SUPPORT FACILITIES: THE PERIMETER FENCE WAS WALKED & CHECKED FOR MOVEMENT (SAGGING). AT THIS TIME, THE FENCE IS HOLDING UP VERY WELL & NO EVIDENCE OF CATTLE ACCESS WAS OBSERVED.

Copy of report mailed to Al Gordon (WSM); Joe Helfrich (DOGM); Brian Smith (OSM)

Copy of report ~~given~~ FILED to PFO

Inspector's signature William A. Warnock No. 30

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE