0005

7100

UTAH NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. INA/015/002

Inspection Date 10/15/90

Permittee/Operator Name Western States Minerals Corp.

Business Address 4975 Van Gordon Street

City Wheat Ridge State CO Zip 80033

Mine J.B. King ☐ Surface ☒ Underground ☐ Other

County Emery State UT

Company Official(s) NONE

State Official(s) Susan White

Time of inspection 1:30 ☐ a.m. ☒ p.m. to 3:30 ☐ a.m. ☒ p.m. ☐ Partial ☒ Complete

Date of last inspection 9/28/90 Weather conditions Clear, windy and warm

Acreage 480 ☐ Permitted 30 ☐ Disturbed 30 ☐ Regraded 30 ☐ Seeded 30 ☐ Bonded

Enforcement Action

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☒	☐	☐	☐
2. Signs and markers	☒	☐	☐	☐
3. Topsoil	☐	☐	☒	☐
4. Hydrologic balance				
a Stream channel diversions	☒	☐	☐	☐
b Diversions	☒	☐	☐	☐
c Sediment ponds and impoundments	☒	☐	☐	☐
d Other sediment control measures	☒	☐	☐	☒
e Surface and groundwater monitoring	☒	☐	☐	☐
f Effluent limitations	☒	☐	☐	☑
5. Explosives	☐	☐	☒	☐
6. Development waste and spoil disposal	☒	☐	☐	☐
7. Coal processing waste	☒	☐	☐	☐
8. Noncoal waste	☒	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☒	☐	☐	☐
10. Slides and other damage	☒	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☒	☐
12. Backfilling and grading	☒	☐	☐	☐
13. Revegetation	☒	☐	☐	☐
14. Subsidence control	☒	☐	☐	☐
15. Cessation of operations	☐	☐	☒	☐
16. Roads				
— Construction	☒	☐	☐	☐
— Drainage controls	☒	☐	☐	☐
— Surfacing	☒	☐	☐	☐
— Maintenance	☒	☐	☐	☐
17. Other transportation facilities	☐	☐	☒	☐
18. Support facilities and utility installations	☒	☐	☐	☐

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. INA/015/002

Inspection Date 10/15/90

Please number comments to correspond with topics on previous page.

1. Bonds and permits were reviewed at the Division office. NOV N90-20-5-1 states that the liability insurance is due by 11/2/90
2. Signs and markers were in place
4c. sediment pond was dry, no evidence of discharge
4d. A silt fence ~~at~~ below the highwall, top right has been undercut. A gully is forming off the highwall to the right of the top left silt fence. Several of the silt fences on the property are old and degrading. These silt fences should either be replaced or removed.
4f. No effluent limits were found in the PAP therefore I presume they are not required to report.
13. Revegetation looked spotty. Some areas have excellent establishment others such as the west face of the refuse pile looked poor.
16. During repair of rills (straw) and subsidence cracks the contractor ~~has~~ is establishing roads over the reclaim and undisturbed area. This must stop!

Copy of report mailed to WSM/Frank Filas; OSM/Brian Smith

Copy of report given to Joe Helfrich/DOGM

Inspector's signature Susan M. White No. 35

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE