

pp page

inspection report

Permit No. ACT/015/002

Inspection Date 12/16/91

Permittee/Operator Name Western States Minerals Corp.

Business Address 84 Glen Carran Circle,

City SPARKS State NV Zip 89431

Mine J.B. KING Surface Underground Other

County EMERY State UT.

Company Official(s) NONE

State Official(s) HENRY SAUER

Time of inspection _____: _____ a.m. p.m. to _____: _____ a.m. p.m. Partial Complete

Date of last inspection 11/7/91 Weather conditions Foggy and Cold

Acreage 480 Permitted 30 Disturbed 30 Regraded 30 Seeded 30 Bonded

Enforcement Action N 91-32-6-1

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS		YES	NO	N/A	COMMENTS
1. Permits	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	9. Protection of fish, wildlife, and related environmental values	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
2. Signs and markers	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	10. Slides and other damage	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	11. Contemporaneous reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Hydrologic balance					12. Backfilling and grading	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
- Stream channel diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	13. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
- Diversions	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	14. Subsidence control	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
- Sediment ponds and impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	15. Cessation of operations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
- Other sediment control measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	16. Roads				
- Surface and groundwater monitoring	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	- Construction	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
- Effluent limitations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	- Drainage controls	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	- Surfacing	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Development waste and spoil disposal	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	- Maintenance	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal processing waste	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	17. Other transportation facilities	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Noncoal waste	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	18. Support facilities and utility installations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

INSPECTION REPORT COMMENTS

Permit No. ACT/015/002

Inspection Date 12/16/91

Please number comments to correspond with topics on previous page.

4) Hydrologic Balance - Stream Channel Dimensions:

^{configuration+} The Main Feeder Ditch and the Feeder Ditch were observed on site. Channel dimensions, check dam configurations and locations, rip-rap gradation and shape were ~~measured~~ ^{noted} and ~~found~~ ^{determined} to be inconsistent with the design specification within the permit (see ^{PAR:} UMC 817.44 Appendix 1+2; UMC 817.44 ADDENDUM 10/10/85; UMC 817.44 Figures 1+2). Therefore violation N 41-32-6-1 was issued for failure to comply with the terms and conditions of the approved permit.

← Other sediment control measures:

The majority of the silt fences, especially on the refuse pile, are in need of maintenance. Many fences are destroyed and completely filled with sediments.

5) Development Waste and Spoil Disposal: Gully channels, south of the refuse pile below Portal D have exposed coal waste. Coal waste is 1.5 ft below the soil surface. A sample of this coal waste was taken for laboratory analysis (sample increment 1.5 ft - 2.0 ft). Results of said lab analysis may require further action of the part of the Division.

4) Subsidence: subsidence cracks have formed. They must be filled in and the subsequent disturbance remedied.

Copy of report mailed to DWIGHT CROSSLAND (WSM); BERNIE Freeman (OSM)

Copy of report given to JOE Helfrich (DOG M)

Inspector's signature Henry Bauer No. 32

WHITE - DOGM YELLOW - OSM PINK - PERMITTEE/OPERATOR GOLDENROD - NOV FILE



gph

NO. N 91-32-6-1

notice of violation

To the following Permittee or Operator:

Name WESTERN STATES MINERALS

Mine F.B. KING Surface Underground Other

County EMERY State UT. Telephone (702) 358-3339

Mailing Address ~~7775 JAN GORDON ST~~ 84 Glen Carron Circle
SPARKS, NV. 89431

State Permit No. ACT/015/002

Ownership Category State Federal Fee Mixed

Date of inspection 12/16, 19 91

Time of inspection 2:00 a.m. p.m. to 5:00 a.m. p.m.

Operator Name (other than Permittee) _____

Mailing Address _____

Under authority of the Utah Coal Mining and Reclamation Act, Section 40-10-1 et seq., *Utah Code Annotated*, 1953, the undersigned authorized representative of the Division of Oil, Gas & Mining has conducted an inspection of above mine on above date and has found violation(s) of the act, regulations or required permit condition(s) listed in attachment(s). This notice constitutes a separate Notice of Violation for each violation listed.

You must abate each of these violations within the designated abatement time. You are responsible for doing all work in a safe and workmanlike manner.

The undersigned representative finds that **cessation of mining is** is not expressly or in practical effect required by this notice. For this purpose, "mining" means extracting coal from the earth or a waste pile, and transporting it within or from the mine site.

This notice shall remain in effect until it expires as provided on reverse side of this form, or is modified, terminated or vacated by written notice of an authorized representative of the director of the Division of Oil, Gas & Mining. Time for abatement may be extended by authorized representative for good cause, if a request is made within a reasonable time before the end of abatement period.

CERTIFIED RETURN RECEIPT:

P 879 596 559

Date of service/mailling 12/19/91

Time of service/mailling 12/23/91 10:00 a.m. p.m.

DWIGHT CROSSLAND
Permittee/Operator representative

Title

Signature

HENRY SAUER
Division of Oil, Gas & Mining representative

SENIOR RECLAMATION SOILS SPECIALIST
Title

Henry Sauer
Signature

#32
Identification Number

SEE REVERSE SIDE

WHITE-DOG M YELLOW-OS M PINK-PERMITTEE/OPERATOR GOLDENROD-NOV FILE



NOTICE OF VIOLATION NO. N 91-32-6-1

Violation No. 1 of 1

Nature of violation

Failure to comply with the terms and conditions of the approved permit. Failure to implement and construct the Main Feeder Ditch and the Feeder Ditch in accordance with the design criteria specified in the permit.

Provisions of act, regulations or permit violated

RG14-300-143

Portion of operation to which notice applies

The Main Feeder Ditch and the Feeder Ditch (Map NO. 4050-5-14R).

Remedial action required (including any interim steps)

Construct the Main Feeder Ditch and the Feeder Ditch in accordance with the approved ~~plan~~ permit.

Abatement time (including interim steps)

No later than 5:00 P.M. February 20, 1992.



g. page

inspection report

Permit No. ACT/015/002

Inspection Date _____

Permittee/Operator Name WESTERN STATES MINERALS CORP

Business Address 84 WEN CARRAN CIRCLE

City SPARKS State NV Zip 89431

Mine J.B. KING Surface Underground Other

County EMERY State UT

Company Official(s) NONE

State Official(s) TOM MUNSON

Time of inspection 12:00 a.m. p.m. to 2:00 a.m. p.m. Partial Complete

Date of last inspection 12/16/91 Weather conditions SUNNY

Acreage 480 Permitted 30 Disturbed 30 Regraded 30 Seeded 30 Bonded

Enforcement Action NONE

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	<u>YES</u>	<u>NO</u>	<u>N/A</u>	<u>COMMENTS</u>		<u>YES</u>	<u>NO</u>	<u>N/A</u>	<u>COMMENTS</u>
1. Permits	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	9. Protection of fish, wildlife, and related environmental values	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Signs and markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	10. Slides and other damage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	11. Contemporaneous reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. Hydrologic balance					12. Backfilling and grading	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<u>a</u> Stream channel diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	13. Revegetation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<u>b</u> Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	14. Subsidence control	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<u>c</u> Sediment ponds and impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	15. Cessation of operations	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
<u>d</u> Other sediment control measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	16. Roads				
<u>e</u> Surface and groundwater monitoring	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	- Construction	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<u>f</u> Effluent limitations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	- Drainage controls	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	- Surfacing	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Development waste and spoil disposal	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	- Maintenance	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal processing waste	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	17. Other transportation facilities	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Noncoal waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	18. Support facilities and utility installations	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

WHITE - DOGM YELLOW - OSM PINK - PERMITTEE/OPERATOR GOLDENROD - NOV FILE

INSPECTION REPORT COMMENTS

Permit No. ACT/015/002

Inspection Date 1/22/92

Please number comments to correspond with topics on previous page.

1 Permits - The abatement of NOV # 91-35-6-1 and NOV # 91-35-7-1 have extended to February 15, 1992 per a modification of the NOV on 1/22/92 by Pam Brubaug-Littig. An informal hearing on state violations N91-35-6-1, N91-35-7-1 and N91-32-6-1, J.B. King Mine, has been established for Tuesday, February 11, 1992, beginning at 9:00 AM. The certificate of insurance is currently in effect until 12/31/92.

An annual sediment pond inspection and certification was carried out on 12/20/91, as well as, a subsidence survey per the requirements of the approved permit. This information will be submitted with an annual report by March 31, 1992.

2. Signs and markers - The signs and markers appeared in good repair.

Copy of report mailed to _____

Copy of report given to _____

Inspector's signature _____ No. _____

WHITE - DOGM YELLOW - OSM PINK - PERMITTEE/OPERATOR GOLDENROD - NOV FILE

INSPECTION REPORT COMMENTS

Permit No. ACT/015/002

Inspection Date 1/22/92

Please number comments to correspond with topics on previous page.

4a Stream channel diversions - Both the main channel and feeder ditch diversions are not being maintained in accordance with the approved plan, subject of NOV N 91-32-6-1.

c. The sediment pond was snow covered but appeared dry. The Annual Sed Pond inspection was completed in December.

d. Silt fences were in need of maintenance pending the outcome of the fact of violation hearing to be held on February 11, 1992 at Division offices regarding NOV # N 91-35-7-1 and NOV # N 91-35-6-1.

It was noted that short of major reworking of the refuse pile area and other problem areas that erosion has and will remain unchecked.

Copy of report mailed to DWIGHT CROSSLAND (WSM); BERNIE FREEMAN (OSM)

Copy of report given to JOE HELFRICH (DOG M)

Inspector's signature Tom Munson

No. 25

WHITE - DOGM YELLOW - OSM PINK - PERMITTEE/OPERATOR GOLDENROD - NOV FILE