0018

UTAH NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

get page

inspection report

Permit No. ACT/015/002

Inspection Date 7/5/91

Permittee/Operator Name Western States Minerals

Business Address 4975 Van Gordon St.

City Wheat Ridge, State Co. Zip 80033

Mine J.B King ☐ Surface ☐ Underground ☐ Other

County Emery State Ut.

Company Official(s) None

State Official(s) Bill Malencik

Time of inspection 1:00 ☐ a.m. ☒ p.m. to 4:00 ☐ a.m. ☒ p.m. ☐ Partial ☐ Complete

Date of last inspection June 12, 1991 Weather conditions Clear/Warm

Acreage 480 ☐ Permitted 30 ☐ Disturbed 30 ☐ Regraded 30 ☐ Seeded 30 ☐ Bonded

Enforcement Action None.

← Followup Item

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☒	☐	☐	☐
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☐
— Diversions	☒	☐	☐	☐
— Sediment ponds and impoundments	☒	☐	☐	☒
— Other sediment control measures	☒	☐	☐	☒
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☒	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☒	☐	☐	☒
14. Subsidence control	☒	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☒	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/002

Inspection Date 7/5/91

Please number comments to correspond with topics on previous page.

Sediment Pond. Sediment pond was dry, stable and showed no sign of any discharge through the open channel spillway.

Silt fences. Some silt fences are in need of routine maintenance, The silt fences in question are those where the silt fences have been extended,

Revegetation. The planted vegetation is fair to good in most of the area, but is poor on the refuse area and the reclaimed road.

Followup On Previous Inspection Permittee should address the outstanding two stipulations as outlined in the inspection report of 5/12/91

Copy of report mailed to WSM/Dwight Crossland; OSM/Brian Smith; DOGM/Joe Helfrich

Copy of report ~~given~~ PFO to

Inspector's signature Tim J. Fredrich No. 26

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

7/15/91

an equal opportunity employer