



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt
Governor
Ted Stewart
Executive Director
James W. Carter
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340
801-359-3940 (Fax)
801-538-5319 (TDD)

Handwritten initials/signature

INSPECTION REPORT

Partial: X Complete: X Exploration:
Inspection Date & Time: 12/29/93 1:00pm - 3:00pm
Date of Last Inspection: 12/2/93

Mine Name: J.B. King County: Emery Permit Number: ACT/015/002
Permittee and/or Operator's Name: Western States Minerals Corp.
Business Address: Suite 130, 250 South Rock Blvd., Reno, Nevada 89502
Type of Mining Activity: Underground X Surface Prep. Plant Other
State Official(s): Tom Munson
Company Official(s): None
Federal Official(s): None
Weather Conditions: sunny
Existing Acreage: Permitted-480 Disturbed-30 Regraded- Seeded-30 Bonded-30
Increased/Decreased: Permitted- Disturbed- Regraded- Seeded- Bonded-
Status: Exploration/ Active/ Inactive/ Temporary Cessation/ Bond Forfeiture
Reclamation (Phase I/Phase II/Final Bond Release/Liability Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Table with 5 columns: Item, EVALUATED, N/A, COMMENTS, NOV/ENF. Contains 21 rows of permit conditions and their evaluation status.



INSPECTION REPORT

(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/002

DATE OF INSPECTION: 12/29/93

(Comments are Numbered to Correspond with Topics Listed Above)

1.) Permits - On September 30, 1993 the division received a plan from Western States Minerals regarding the J.B. King Reclamation and the abatement of NOV #91-32-6-1; #93-25-3-1; & #93-25-5-1. Preliminary plans were reviewed by the Division. An extension has been given to February 18, 1994 to submit final plans and implementation of plans will proceed as quickly as practicable.

2.) Signs and Markers - The sign in place at J.B. King lists Western States Minerals as the permittee and the address as 4975 VanGordon St., Wheatridge, Colorado, 80033 and the telephone number as 303-425-7042. This address is considered the corporate address.

4b.) Sediment ponds and impoundments- The sediment pond was dry at the time of inspection. The last pond inspection was submitted to the Division on 10/8/93 and indicated no problems. A certified annual report was received by the Division on January 11, 1993 based on an inspection carried out on December 24, 1992. No certified Annual report for 1993 has been received todate.

9. Protection of Fish, Wildlife and Related environmental Values

The two fences which were down as of the last inspection had been repaired and no new access was noted.

Copy of this Report:

Mailed to: Bernie Freeman (OSM), E. M. Gerick (WSMC)

Given to: Joe Helfrich (DOGM)

Inspector's Signature: _____



#25

Date: 12/29/93