



pgl

NO. N 93-25-2-1

To the following Permittee or Operator:

Name WESTERN STATES MINERAL CORP.

Mine J.B. KING MINE Surface Underground Other

County EMERY State UTAH Telephone _____

Mailing Address SUITE 130, 250 SOUTH ROCK BLVD., RENO, NV, 89502

State Permit No. ACT/015/002

Ownership Category State Federal Fee Mixed

Date of inspection 5/11/93, 19____

Time of inspection 9:00 a.m. p.m. to 2:00 a.m. p.m.

Operator Name (other than Permittee) _____

Mailing Address _____

notice of violation

Under authority of the Utah Coal Mining and Reclamation Act, Section 40-10-1 et seq., *Utah Code Annotated*, 1953, the undersigned authorized representative of the Division of Oil, Gas & Mining has conducted an inspection of above mine on above date and has found violation(s) of the act, regulations or required permit condition(s) listed in attachment(s). This notice constitutes a separate Notice of Violation for each violation listed.

You must abate each of these violations within the designated abatement time. You are responsible for doing all work in a safe and workmanlike manner.

The undersigned representative finds that **cessation of mining is** **is not** expressly or in practical effect required by this notice. For this purpose, "mining" means extracting coal from the earth or a waste pile, and transporting it within or from the mine site.

This notice shall remain in effect until it expires as provided on reverse side of this form, or is modified, terminated or vacated by written notice of an authorized representative of the director of the Division of Oil, Gas & Mining. Time for abatement may be extended by authorized representative for good cause, if a request is made within a reasonable time before the end of abatement period.

Certified Return Receipt P 074 975 406

Date of service/mailing 5-13-93

Time of service/mailing 10:00 a.m. p.m.

E.M. GERICK
Permittee/Operator representative

Title

Signature

Tom Munson
Division of Oil, Gas & Mining representative

Rec. Specialist #25
Title

Tom Munson
Signature

#25
Identification Number

SEE REVERSE SIDE

WHITE-DOG M YELLOW-OS M PINK-PERMITTEE/OPERATOR GOLDENROD-NOV FILE



NOTICE OF VIOLATION NO. N 93-25-2-1

Violation No. 1 of 1

Nature of violation

The undisturbed diversion above the refuse pile behind the revegetation test plot is not preventing to the extent possible using the best technology currently available, additional contributions of suspended solids to streamflow outside the permit area

Provisions of act, regulations or permit violated

R 645-301-742.312.3

R 645-301-742.121

Portion of operation to which notice applies

The undisturbed diversion behind the revegetation test plot.

Remedial action required (including any interim steps)

To prevent to the extent possible additional contributions of suspended solids from getting into the undisturbed diversion

Abatement time (including interim steps)

thirty days after receipt of N.O.V.