

Document Information Form

Mine Number: C/015/002

File Name: Incoming

To: DOGM

From:

Person Jim Blackburn

Company N/A

Date Sent: August 8, 1994

Explanation:

Pond Inspection Report

cc:


File in:
C/015, 002, Incoming

- Refer to:
- Confidential
 - Shelf
 - Expandable

Date _____ For additional information

3rd qtr insp

POND INSPECTION REPORT



POND: Sediment

LOCATION: 13 King mine

Route to station
pen file REMARKS ACT/015/002 #6

ITEM
(1) Potential Safety Hazards

NONE

(2) Slope Stability

Good

(3) Erosion

very little

(4) Construction and Maintenance Performance Standards

Good

(5) Recommendations/Comments

Just a trace of
row off in pond

I have performed the above inspection on this pond and do hereby certify it to be a true and accurate representation of the pond at this time.

Jim Blackbe

8/13/94 Date

File in:
 Confidential
 Shelf
 Expandable
Refer to Record No. 0029 Date 8-8-94
In CI 015, 002, Incoming
For additional information