

### Document Information Form

Mine Number: C/015/002

File Name: Incoming

To: DOGM

**From:**

Person Jim Blackburn

Company N/A

Date Sent: April 22, 1994

**Explanation:**

Pond Inspection Report

\_\_\_\_\_  
\_\_\_\_\_

cc:


File in: C/015, 002, Incoming

- Refer to:
- Confidential
  - Shelf
  - Expandable

Date \_\_\_\_\_ For additional information

2nd qrt 1997

POND INSPECTION REPORT



POND: Sediment

LOCATION: 13 King mine

Route to Sma dra file  
REMARKS ACT/015/002 #6

ITEM  
(1) Potential Safety Hazards

NONE

(2) Slope Stability

Good

(3) Erosion

very little

(4) Construction and Maintenance Performance Standards

Good

(5) Recommendations/Comments

I have performed the above inspection on this pond and do hereby certify it to be a true and accurate representation of the pond at this time.

Jim Blacklow

4/19/97  
Date

File in:

- Confidential
- Shelf
- Expandable

Refer to Record No 0036 Date 4-22-97

In Cl 015, 002, Incoming

For additional information