



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

INSPECTION REPORT

Handwritten initials/signature

Michael O. Leavitt
Governor
Ted Stewart
Executive Director
James W. Carter
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340
801-359-3940 (Fax)
801-538-5319 (TDD)

Partial: X Complete: Exploration:
Inspection Date & Time: 10/15/94 1:00 TO 3:30
Date of Last Inspection: 9/22/94

Mine Name: J.B. King County: Emery Permit Number: ACT/015/002

Permittee and/or Operator's Name: Western States Minerals Corp.

Business Address: Suite 130, 250 South Rock Blvd., Reno, Nevada 89502

Type of Mining Activity: Underground X Surface Prep. Plant Other

State Official(s): Susan White

Company Official(s): None

Federal Official(s): None

Weather Conditions: Cloudy and cool

Existing Acreage: Permitted-480 Disturbed-30 Regraded- Seeded-30 Bonded-30

Increased/Decreased: Permitted- Disturbed- Regraded- Seeded- Bonded-

Status: Exploration/ Active/ Inactive/ Temporary Cessation/ Bond Forfeiture

Reclamation (Phase I/ Phase II/ Final Bond Release/ Liability Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

Table with 5 columns: Item, EVALUATED, N/A, COMMENTS, NOV/ENF. Rows include: PERMITS, CHANGE, TRANSFER, RENEWAL, SALE; SIGNS AND MARKERS; TOPSOIL; HYDROLOGIC BALANCE; EXPLOSIVES; DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES; COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS; NONCOAL WASTE; PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES; SLIDES AND OTHER DAMAGE; CONTEMPORANEOUS RECLAMATION; BACKFILLING AND GRADING; REVEGETATION; SUBSIDENCE CONTROL; CESSATION OF OPERATIONS; ROADS; CONSTRUCTION/MAINTENANCE/SURFACING; DRAINAGE CONTROLS; OTHER TRANSPORTATION FACILITIES; SUPPORT FACILITIES/UTILITY INSTALLATIONS; AVS CHECK (4th Quarter-April, May, June) (date); AIR QUALITY PERMIT; BONDING & INSURANCE.



INSPECTION REPORT

(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/002

DATE OF INSPECTION: 10/15/94

(Comments are Numbered to Correspond with Topics Listed Above)

3. TOPSOIL

Evidence of water flow thru the existing rills and gullies was observed on site.

4. HYDROLOGIC BALANCE:

b. **Sediment Ponds and Impoundments** - Water was observed in the pond.

9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES

Evidence of an animal burrowing was observed on site. Presumably a badger was "digging out" rodent burrows in pursuit of a meal. In this process the animal uprooted or exposed the roots of 30 to 50 shrubs. While this single episode was not enough to jeopardize the woody plant success for the site, repeated events would warrant intervention and consultation with the Utah Division of Wildlife Resources.

13. REVEGETATION

The Cheatgrass had germinated and showed greening with the recent rains. The soils on site were generally moist from the rains.

Copy of this Report:

Mailed to: Tom Ehmett (OSM), E.M. Gerick (WSMC)

Given to: Joe Helfrich (DOGM)

Inspector's Signature:

Susan M. White

#35

Date: 10/26/94