



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

INSPECTION REPORT

Michael O. Leavitt
Governor
Ted Stewart
Executive Director
James W. Carter
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340
801-359-3940 (Fax)
801-538-5319 (TDD)

Partial: X Complete: Exploration:
Inspection Date & Time: 7/21/94 2:00 TO 3:00
Date of Last Inspection: 6/9/94

Mine Name: J.B. King County: Emery Permit Number: CT/015/002
Permittee and/or Operator's Name: Western States Minerals Corp.
Business Address: Suite 130, 250 South Rock Blvd., Reno, Nevada 89502
Type of Mining Activity: Underground X Surface Prep. Plant Other
State Officials(s): Susan White
Company Official(s): None
Federal Official(s): None
Weather Conditions: Fair and Hot
Existing Acreage: Permitted-480 Disturbed-30 Regraded- Seeded-30 Bonded-30
Increased/Decreased: Permitted- Disturbed- Regraded- Seeded- Bonded-
Status: Exploration/ Active/ Inactive/ Temporary Cessation/ Bond Forfeiture
Reclamation (Phase I/Phase II/ Final Bond Release/ Liability Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

Table with 4 columns: EVALUATED, N/A, COMMENTS, NOV/ENF. Rows include: PERMITS, CHANGE, TRANSFER, RENEWAL, SALE; SIGNS AND MARKERS; TOPSOIL; HYDROLOGIC BALANCE; EXPLOSIVES; DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES; COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS; NONCOAL WASTE; PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES; SLIDES AND OTHER DAMAGE; CONTEMPORANEOUS RECLAMATION; BACKFILLING AND GRADING; REVEGETATION; SUBSIDENCE CONTROL; CESSATION OF OPERATIONS; ROADS; OTHER TRANSPORTATION FACILITIES; SUPPORT FACILITIES/UTILITY INSTALLATIONS; AVS CHECK; AIR QUALITY PERMIT; BONDING & INSURANCE.



## INSPECTION REPORT

(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/002

DATE OF INSPECTION: 7/21/94

(Comments are Numbered to Correspond with Topics Listed Above)

#### 4. HYDROLOGIC BALANCE:

c. **Other Sediment Control Measures** - The silt fence along the top of the refuse pile was in good repair.

#### 13. REVEGETATION

The site was very dry, weeds were not as lush as in previous years. Halogeton appeared to be prevalent on site.

Copy of this Report:

Mailed to: Bernie Freeman (OSM), E.M. Gerick (WSMC)

Given to: Joe Helfrich (DOGM)

Inspector's Signature: Juan M. White #35 Date: 9/16/94