

0012



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

INSPECTION REPORT

gjh

Michael O. Leavitt
Governor
Ted Stewart
Executive Director
James W. Carter
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340
801-359-3940 (Fax)
801-538-5319 (TDD)

Partial: Complete: Exploration:
Inspection Date & Time: 6/9/94 9 to 1
Date of Last Inspection: 5/25/94

Mine Name: J.B. King County: Emery Permit Number: ACT/015/002
Permittee and/or Operator's Name: Western States Minerals Corp.
Business Address: Suite 130, 250 South Rock Blvd., Reno, Nevada 89502
Type of Mining Activity: Underground Surface Prep. Plant Other
State Official(s): Susan White
Company Official(s): Sam Bamberg and Ingrid Hanne (Bamberg Associates)
Federal Official(s): None
Weather Conditions: Warm and buggy
Existing Acreage: Permitted-480 Disturbed-30 Regraded- Seeded-30 Bonded-30
Increased/Decreased: Permitted- Disturbed- Regraded- Seeded- Bonded-
Status: Exploration/ Active/ Inactive/ Temporary Cessation/ Bond Forfeiture
Reclamation (Phase I/ Phase II/ Final Bond Release/ Liability Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- Substantiate the elements on this inspection by checking the appropriate performance standard.
 - For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - For partial inspections check only the elements evaluated.
- Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	EVALUATED	N/A	COMMENTS	NOV/ENF
1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. SIGNS AND MARKERS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. TOPSOIL	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. HYDROLOGIC BALANCE:				
a. DIVERSIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
b. SEDIMENT PONDS AND IMPOUNDMENTS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
c. OTHER SEDIMENT CONTROL MEASURES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
d. WATER MONITORING	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
e. EFFLUENT LIMITATIONS	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. EXPLOSIVES	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. NONCOAL WASTE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. SLIDES AND OTHER DAMAGE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. CONTEMPORANEOUS RECLAMATION	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. BACKFILLING AND GRADING	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. REVEGETATION	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
14. SUBSIDENCE CONTROL	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
15. CESSATION OF OPERATIONS	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16. ROADS:				
a. CONSTRUCTION/MAINTENANCE/SURFACING	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
b. DRAINAGE CONTROLS	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. OTHER TRANSPORTATION FACILITIES	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. SUPPORT FACILITIES/UTILITY INSTALLATIONS	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
19. AVS CHECK (4th Quarter-April, May, June) _____ (date)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
20. AIR QUALITY PERMIT	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. BONDING & INSURANCE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>



INSPECTION REPORT

(Continuation sheet)

Page 2 of 3

PERMIT NUMBER: ACT/015/002

(Comments are Numbered to Correspond with Topics Listed Above)

2. SIGNS AND MARKERS

Signs and markers were in place. The permit entry sign was unchanged.

4. HYDROLOGIC BALANCE

a. Diversions - The diversion on site is not in compliance with the approve plan and is currently being corrected in association with NOV N91-32-6-1. The abatement date for this violation has been extended to August 1994.

b. Sediment Ponds and Impoundments - The 1993 annual pond certification was performed January 21, 1994 and certified by Barry Barnum. This report was submitted in the 1993 Annual Report. No structural weakness or other hazardous conditions were noted. The existing storage capacity was deemed adequate.

The first quarter pond inspection was completed by Jim Blackburn and indicated no problems. During the site inspection the pond was dry. No evidence of water ponding was noted this year.

c. Other Sediment Control Measures - The silt fence on top of the refuse pile at the east boundary was in good repair.

13. REVEGETATION

At the time of this inspection Sam Bamberg and Ingrid Hanne were on site conducting vegetation surveys. Efforts of this vegetation survey is to assess the vegetation patterns on the reclaimed site and in the undisturbed areas adjacent to the site.

14. SUBSIDENCE CONTROL

The 1993 annual subsidence monitoring was performed on January 21, 1994 and reported to the Division in the 1993 Annual Report. No significant elevational change was noted.

19. AVS CHECK

The permit entry sign contains the same address and phone number as found in the permit. A phone call to Buzz Gerick on June 20, 1994 confirmed that the permit information of Identification of Interests is still current.

INSPECTION REPORT

(Continuation sheet)

Page 3 of 3

PERMIT NUMBER: ACT/015/002

21. BONDING & INSURANCE

Liability insurance carried by Reliance Insurance Company expires 4/1/95.
The bond in the amount of \$126,078 is held by Seaboard Surety Company.

Copy of this Report:

Mailed to: Bernie Freeman (OSM), E.M. Gerick (WSMC)

Given to: Joe Helfrich (DOGM)

Inspector's Signature: Susan M. White #35 Date: 6/22/94