

0013



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

INSPECTION REPORT

Handwritten initials/signature

Michael O. Leavitt
Governor
Ted Stewart
Executive Director
James W. Carter
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340
801-359-3940 (Fax)
801-538-5319 (TDD)

Partial: X Complete: Exploration:
Inspection Date & Time: 5/25/94 1 to 3
Date of Last Inspection: 4/14/94

Mine Name: J.B. King County: Emery Permit Number: ACT/015/002
Permittee and/or Operator's Name: Western States Minerals Corp.
Business Address: Suite 130, 250 South Rock Blvd., Reno, Nevada 89502
Type of Mining Activity: Underground X Surface Prep. Plant Other
State Officials(s): Susan White
Company Official(s): None
Federal Official(s): None
Weather Conditions: Partly cloudy and windy
Existing Acreage: Permitted-480 Disturbed-30 Regraded- Seeded-30 Bonded-30
Increased/Decreased: Permitted- Disturbed- Regraded- Seeded- Bonded-

Status: Exploration/ Active/ Inactive/ Temporary Cessation/ Bond Forfeiture
Reclamation (Phase I/Phase II/Final Bond Release/ Liability Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

Table with 5 columns: Item, EVALUATED, N/A, COMMENTS, NOV/ENF. Rows include: PERMITS, CHANGE, TRANSFER, RENEWAL, SALE; SIGNS AND MARKERS; TOPSOIL; HYDROLOGIC BALANCE; EXPLOSIVES; DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES; COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS; NONCOAL WASTE; PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES; SLIDES AND OTHER DAMAGE; CONTEMPORANEOUS RECLAMATION; BACKFILLING AND GRADING; REVEGETATION; SUBSIDENCE CONTROL; CESSATION OF OPERATIONS; ROADS; OTHER TRANSPORTATION FACILITIES; SUPPORT FACILITIES/UTILITY INSTALLATIONS; AVS CHECK; AIR QUALITY PERMIT; BONDING & INSURANCE.

INSPECTION REPORT

(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/002

(Comments are Numbered to Correspond with Topics Listed Above)

Tracks from the drill rig were observed. The drilling is part of the process to redesign the on site drainages and refuse area. Minimal damage was observed from the drill operation.

13. REVEGETATION

Numerous weedy species were observed on site. Dominant weedy species this month were Cheatgrass, Malcolmia, and Poverty weed(?). The vegetation in the drainage area looked good, however vegetation is lacking on other areas of the mine site.

14. SUBSIDENCE CONTROL

Small cracks were noted in the subsidence area on the previous inspection. No cracks were observed on the current inspection. Either the operator filled the cracks or natural sloughing took place to fill the cracks. Animal burrows were numerous along the subsidence fault line.

Copy of this Report:

Mailed to: Bernie Freeman (OSM), E.M. Gerick (WSMC)

Given to: Joe Helfrich (DOGM)

Inspector's Signature: Susan M. White #35 Date: 5/31/94