

0007

### Document Information Form

Mine Number: C/015/002

File Name: Incoming

To: DOGM

From:

Person Jim Blackburn

Company N/A

Date Sent: October 07, 1996

Explanation:

Pond Inspection Report


cc:

File in:  
C/\_\_\_\_\_, \_\_\_\_\_, Incoming

Refer to:

- Confidential
- Shelf
- Expandable

Date \_\_\_\_\_ For additional information



POND INSPECTION REPORT  
DIV. OF OIL, GAS & MINING

LOCATION: S15 King mine

POND: Sediment

ITEM	REMARKS
(1) Potential Safety Hazards	<u>NONE</u>
(2) Slope Stability	<u>Good</u>
(3) Erosion	<u>very little</u>
(4) Construction and Maintenance Performance Standards	<u>Good</u>
(5) Recommendations/Comments	<u>Pond 3/4 full of water</u>
	<u>cleaned sediment + ditch 110<sup>th</sup> 9/26/96</u>

I have performed the above inspection on this pond and do hereby certify it to be a true and accurate representation of the pond at this time.

Jim Blukler  
10/4/96 Date

File in:  
 Confidential  
 Shelf  
 Expandable  
Refer to Record No 0007 Date 10-7-96  
In C/ 015, 002, Incoming  
For additional information