

Document Information Form

Mine Number: C/015/002

File Name: Incoming

To: DOGM

From:

Person Jim Blackburn

Company N/A

Date Sent: July 10, 1997

Explanation:

Pond Inspection Report

cc:


File in: C/015, 002, Incoming

Refer to:

- Confidential
- Shelf
- Expandable

Date _____ For additional information

3rd qrt inspt



POND INSPECTION REPORT

POND: Sediment

LOCATION: J13 King mine

Route to SW
Jan file # 1102/002
#6

ITEM
(1) Potential Safety Hazards

REMARKS

None

(2) Slope Stability

Good

(3) Erosion

very little

(4) Construction and Maintenance Performance Standards

Good

(5) Recommendations/Comments

pond dry

I have performed the above inspection on this pond and do hereby certify it to be a true and accurate representation of the pond at this time.

Jim Blankenship

7/8/97 Date

File in:

- Confidential
- Shelf
- Expandable

Refer to Record No 0006 Date 7-10-97

In C/ 015, 002, Incoming

For additional information