


PHOTOS OF  
— EROSION MONITORING STATIONS —  
J.B. KING NOV. 3 & 5, 1997

Photos of  
EROSION MONITORING STATIONS  
J.B. KING MINE  
November 3 & 5, 1997



December 15, 1997



Ms. Susan White  
State of Utah  
Division of Oil, Gas & Mining  
1594 West North Temple, Suite 1210  
P.O. 145801  
Salt Lake City, Utah 84114-5801

**RE: Transmittal of photographic albums taken of the Erosional Monitoring Transects - J.B. King Reclaimed Minesite, ACT/015/002, Folder #2, Emery County, Utah**

Dear Susan:

*Copy Susan (letter)*


Included in this transmittal are the following photographic albums:

1. Photos of Erosional Monitoring Transects taken November 12, 1996. Also included with these photos are revised schematic drawings of the Erosional Monitoring Stations showing actual measurements taken during the same time period.
2. Photos of Erosional Monitoring Transects taken May 14, 1997. Also included in this album is a photo of the sign repairs that were completed during that same time period.
3. Photos of Erosional Monitoring Transects taken November 3 & 5, 1997. Also included in this album is a photo of the new spillway that was constructed for the sedimentation pond.

If you have any questions concerning this information, please call me at your convenience. I want to wish you and your family the warmest greetings for a very Christ-filled Christmas season.

Sincerely,

E.M. (Buzz) Gerick  
Vice President of Operations



## **EROSION MONITORING STATIONS**

**for the**

**J. B. King Mine**

**F-Series and A to D Series - X & L Sections  
Photos taken November 3 & 5, 1997**

**Prepared by Western States Minerals Corporation**