

PHOTOS OF
— EROSIONAL MONITORING TRANSECTS —
J.B. KING MAY 14, 1997

WESTERN STATES MINERALS CORPORATION

December 15, 1997

RECEIVED
DEC 19 1997
DIV. OF OIL, GAS & MINING

Ms. Susan White
State of Utah
Division of Oil,Gas & Mining
1594 West North Temple, Suite 1210
P.O. 145801
Salt Lake City, Utah 84114-5801

RE: Transmittal of photographic albums taken of the Erosional Monitoring Transects - J.B. King Reclaimed Minesite, ACT/015/002, Folder #2, Emery County, Utah

Copy Susan (letter)

Dear Susan:

Included in this transmittal are the following photographic albums:

1. Photos of Erosional Monitoring Transects taken November 12, 1996. Also included with these photos are revised schematic drawings of the Erosional Monitoring Stations showing actual measurements taken during the same time period.

2. Photos of Erosional Monitoring Transects taken May 14, 1997. Also included in this album is a photo of the sign repairs that were completed during that same time period.

3. Photos of Erosional Monitoring Transects taken November 3 & 5, 1997. Also included in this album is a photo of the new spillway that was constructed for the sedimentation pond.

If you have any questions concerning this information, please call me at your convenience. I want to wish you and your family the warmest greetings for a very Christ-filled Christmas season.

Sincerely,

E.M. Gerick

E.M. (Buzz) Gerick
Vice President of Operations

250 S. Rock Blvd., Suite 130 ▲ Reno, NV 89502 ▲ (702) 856-3339 ▲ FAX (702) 856-1818

RECEIVED
DEC 19 1997
DIV. OF OIL, GAS & MINING

EROSION MONITORING STATIONS

for the

J. B. King Mine

F-Series and A to D Series - X & L Sections
Photos taken May 14, 1997

Prepared by Western States Minerals Corporation