



# INSPECTION REPORT

(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/002

DATE OF INSPECTION: 12/22/97

(Comments are Numbered to Correspond with Topics Listed Above)

A small amount of snow was visible.

## 2. SIGNS AND MARKERS:

The permit entry sign was in good condition.

## 4. HYDROLOGIC BALANCE:

The sediment pond was iced over.

Copy of this Report:

Mailed to: OSM, E.M. Gerick (WSMC)

Given to: Joe Helfrich (DOGM)

Inspector's Signature: Susan White #35 Date: 1/9/97