

Document Information Form

Mine Number: C/015/002

File Name: Incoming

To: DOGM

From:

Person Jim Blackburn

Company N/A

Date Sent: October 09, 1998

Explanation:

Pond Inspection Report

cc:

File in: C/015, 002, Incoming

Refer to:

- Confidential
- Shelf
- Expandable

Date _____ For additional information

ACT 1015/002 #10

41. f inspt 98

Susan

POND INSPECTION REPORT

RECEIVED
OCT 09 1998

POND: Sediment

LOCATION: JB King mine

DIV. OF OIL, GAS & MINING

REMARKS

ITEM

(1) Potential Safety Hazards

None

(2) Slope Stability

Good

(3) Erosion

very little

(4) Construction and Maintenance Performance Standards

Good

(5) Recommendations/Comments

drainage ditch worth
refuge pile washed out

I have performed the above inspection on this pond and do hereby certify it to be a true and accurate representation of the pond at this time.

Susan Bludner

10/7/98

Date

File in:

- Confidential
- Shelf
- Expandable

Refer to Record No 0002 Date 10-9-98

In C/015, 002, Incoming

For additional information