

0013

Document Information Form

Mine Number: C/015/002

File Name: Incoming

To: DOGM

From:

Person Jim Blackburn

Company N/A

Date Sent: January 21, 1998

Explanation:

Pond Inspection Report.


cc:

File in: C/015, 002, Incoming

Refer to:

- Confidential
- Shelf
- Expandable

Date _____ For additional information



POND INSPECTION REPORT

POND: Sediment

LOCATION: J.B. King Mine
ACT 1015/002 #6
Route to Snow,
then file

ITEM
(1) Potential Safety Hazards

NONE

(2) Slope Stability

Good

(3) Erosion

Very little

(4) Construction and Maintenance Performance Standards

Good

(5) Recommendations/Comments

3 in snow
pond frozen over

I have performed the above inspection on this pond and do hereby certify it to be a true and accurate representation of the pond at this time.

Jim Bludner
1/15/98
Date

File in:
 Confidential
 Shelf
 Expandable
Refer to Record No 0013 Date 1-21-98
In C/ 015, 002, Incoming
For additional information