

INSPECTION REPORT

(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/002

DATE OF INSPECTION: 1/15/98

(Comments are Numbered to Correspond with Topics Listed Above)

A small amount of snow had fallen the morning of the visit.

2. SIGNS AND MARKERS:

The permit entry sign was in good condition.

4. HYDROLOGIC BALANCE:

The sediment pond was iced over.

The work done by the Operator in 1994 on the refuse pile was nominated by the Division to the Board for an Earth Day Award.

Copy of this Report:

Mailed to: OSM, E.M. Gerick (WSMC)

Given to: Joe Helfrich (DOGM)

Inspector's Signature: Susan M. White #35 Date: 2/6/98