


POND INSPECTION REPORT

POND: Sediment

LOCATION: J B King Mine

<u>ITEM</u>	<u>REMARKS</u>
(1) Potential Safety Hazards	<u>None</u>
(2) Slope Stability	<u>Good</u>
(3) Erosion	<u>very little</u>
(4) Construction and Maintenance Performance Standards	<u>Good</u>
(5) Recommendations/Comments	<u>water still in pond</u>

I have performed the above inspection on this pond and do hereby certify it to be a true and accurate representation of the pond at this time.




\_\_\_\_\_

\_\_\_\_\_

Date

1st grt inspection 1999

ACT 1015/002 #  
SUSAN



POND INSPECTION REPORT

POND: sediment

LOCATION: J.B King mine

<u>ITEM</u>	<u>REMARKS</u>
(1) Potential Safety Hazards	None
(2) Slope Stability	Good
(3) Erosion	very little
(4) Construction and Maintenance Performance Standards	Good
(5) Recommendations/Comments	None

I have performed the above inspection on this pond and do hereby certify it to be a true and accurate representation of the pond at this time.

Susan Blumberg

1/4/99  
Date