0018

DQH

State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt
Governor
Kathleen Clarke
Executive Director
Lowell P. Braxton
Division Director

1594 West North Temple, Suite 1210
PO Box 145801
Salt Lake City, Utah 84114-5801
801-538-5340
801-359-3940 (Fax)
801-538-7223 (TDD)

INSPECTION REPORT

Partial: X Complete:____ Exploration:___
Inspection Date & Time: 8/26/99, 9:00 a.m. to 12:00 noon
Date of Last Inspection: 7/16/99

Mine Name: J.B. King County: Emery Permit Number: **ACT/015/002**
Permittee and/or Operator's Name: Western States Minerals Corp.
Business Address: Suite 130, 250 South Rock Blvd., Reno, Nevada 89502
Type of Mining Activity: Underground X Surface__ Prep. Plant__ Other__
State Officials(s): Robert Davidson
Company Official(s):_____
Federal Official(s):_____
Weather Conditions: Clear, sunny, warm, slight breeze
Existing Acreage: Permitted-480 Disturbed-30 Regraded-___ Seeded-30 Bonded-30
Increased/Decreased: Permitted-__ Disturbed-__ Regraded-__ Seeded-__ Bonded-__
Status: __Exploration/__Active/__Inactive/__Temporary Cessation/__Bond Forfeiture
Reclamation (__Phase I/__Phase II/__Final Bond Release/__Liability_____Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions
1. Substantiate the elements on this inspection by checking the appropriate performance standard.
   a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
   b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

		Evaluated	N/A	Comments	NOV/ENF
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	[ ]	[ ]	[ ]	[ ]
2.	SIGNS AND MARKERS	[X]	[ ]	[X]	[ ]
3.	TOPSOIL	[ ]	[ ]	[ ]	[ ]
4.	HYDROLOGIC BALANCE:				
a.	DIVERSIONS	[X]	[ ]	[X]	[ ]
b.	SEDIMENT PONDS AND IMPOUNDMENTS	[X]	[ ]	[X]	[ ]
c.	OTHER SEDIMENT CONTROL MEASURES	[X]	[ ]	[X]	[ ]
d.	WATER MONITORING	[ ]	[ ]	[ ]	[ ]
e.	EFFLUENT LIMITATIONS	[ ]	[ ]	[ ]	[ ]
5.	EXPLOSIVES	[ ]	[ ]	[ ]	[ ]
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	[ ]	[ ]	[ ]	[ ]
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	[ ]	[ ]	[ ]	[ ]
8.	NONCOAL WASTE	[ ]	[ ]	[ ]	[ ]
9.	PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	[X]	[ ]	[X]	[ ]
10.	SLIDES AND OTHER DAMAGE	[ ]	[ ]	[ ]	[ ]
11.	CONTEMPORANEOUS RECLAMATION	[ ]	[ ]	[ ]	[ ]
12.	BACKFILLING AND GRADING	[ ]	[ ]	[ ]	[ ]
13.	REVEGETATION	[X]	[ ]	[X]	[ ]
14.	SUBSIDENCE CONTROL	[ ]	[ ]	[ ]	[ ]
15.	CESSATION OF OPERATIONS	[ ]	[ ]	[ ]	[ ]
16.	ROADS:				
a.	CONSTRUCTION/MAINTENANCE/SURFACING	[ ]	[ ]	[ ]	[ ]
b.	DRAINAGE CONTROLS	[ ]	[ ]	[ ]	[ ]
17.	OTHER TRANSPORTATION FACILITIES	[ ]	[ ]	[ ]	[ ]
18.	SUPPORT FACILITIES/UTILITY INSTALLATIONS	[ ]	[ ]	[ ]	[ ]
19.	AVS CHECK (4th Quarter-April, May, June)_____(date)	[ ]	[ ]	[ ]	[ ]
20.	AIR QUALITY PERMIT	[ ]	[ ]	[ ]	[ ]
21.	BONDING & INSURANCE	[ ]	[ ]	[ ]	[ ]

INSPECTION REPORT

(Continuation sheet)

PERMIT NUMBER: ACT/015/002

DATE OF INSPECTION: 8/26/99

(Comments are Numbered to Correspond with Topics Listed Above)

2. SIGNS AND MARKERS

The lower and upper permit entry signs are both in good condition.

4. HYDROLOGIC BALANCE

a. DIVERSIONS

There is evidence of recent storm events since the last inspection.

The main interior channels continue to widen. Down cutting seems to have slowed; the bottom of the channels are armored with large rock that has been deposited.

The north diversion ditch has contained flows with recent storm events. The central deposition zone seems to have equilibrated.

b. SEDIMENT PONDS AND IMPOUNDMENTS

The sediment pond is approximately ½ full with water.

c. OTHER SEDIMENT CONTROL MEASURES

The ridge pocked area has performed well with recent storm events by obviously containing all runoff. Sediment has collected in the pocks. Vegetation includes some grasses and few shrubs.

9. PROTECTION OF FISH, WILDLIFE AND OTHER RELATED VALUES

Both the bottom front and upper entrance gates were secured and closed. The entire site perimeter fence is in place.

13. REVEGETATION

Snakeweed and rabbit brush are blooming. Winter fat has gone to seed. There is no recent sign of cattle within the site.

Copy of this Report:

Mailed to: OSM, E.M. Gerick (WSMC)

Given to: Daron Haddock (DOGM)

Inspector's Signature: _____ #45 Date: 8/26/99

H:\WPFILES\COAL\015002.jbk\INSP0826.PAR.wpd