0013

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. INA/015/0041

Inspection Date 7/20/88

Permittee/Operator Name Beaver Creek Coal Co.

Business Address P.O. Box 1378

City Price State Ut Zip 84501

Mine Huntington #4 ☐ Surface ☒ Underground ☐ Other

County Emery State Ut.

Company Official(s) NA

State Official(s) Bill Malencik & Bill Wakmack

Time of inspection 8:00 ☒ a.m. ☐ p.m. to 12:00 ☐ a.m. ☐ p.m. ☒ Partial ☐ Complete

Date of last inspection 6/8/88 Weather conditions Clear Dry.

Acreage 2600 ☐ Permitted 125 ☐ Disturbed 12 ☐ Regraded 12 ☐ Seeded 125 ☐ Bonded

Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☒	☐	☐	☐
3. Topsoil	☒	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☐
— Diversions	☒	☐	☐	☒
— Sediment ponds and impoundments	☐	☐	☐	☐
— Other sediment control measures	☒	☐	☐	☒
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☒	☐
6. Development waste and spoil disposal	☐	☐	☒	☐
7. Coal processing waste	☐	☐	☒	☐
8. Noncoal waste	☐	☐	☒	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☒	☐	☐	☒
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☒	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☒	☐
18. Support facilities and utility installations	☐	☐	☒	☐

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. INA/015/004

Inspection Date 7/20/88

Please number comments to correspond with topics on previous page.

General Comments. Dan Guy was on vacation. No mine company representatives were available to accompany the DOGM inspectors. Environmental conditions at the mine site were in full compliance. Some maintenance items are underscored herein and do not constitute a violation of the regulations and/or other guidlines.

Maintenance Items

1 Repair broken top barb wire on lower pad parking area

2- Repair silt fence below the top soil pile

3- Place berm adjacent to culvert near pumphouse area and contiguous to a road culvert.

Revegetation. Grass covered on most areas was excellent. All had matured but was still in the green stage. Soil samples have been taken on those areas to be retreated this fall.

USFS. Two seasonal USFS employees were controlling weeds along the USFS access road to the mine

Copy of report mailed to SLC FOR Brian Smith; Joe Helfrich

Copy of report ~~given~~ filed to BCCC - FOR DAN GUY PFO

Inspector's signature Wm. J. Malinick No. 26

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

7/22/88

DOGM/IR-2 an equal opportunity employer 11/86 001049