4-14-89 7093

0011

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

gdh RUS

inspection report

Permit No. INA/015/004

Inspection Date March 31, April 3, 1989.

Permittee/Operator Name Beaver Creek Coal Co.

Business Address P.O. Box 1378

City Price State Utah Zip 84501

Mine Huntington #4 ☐ Surface ☒ Underground ☐ Other

County Emery State Ut

Company Official(s) Dan Guy

State Official(s) Bill Malehick

Time of inspection 8:00 ☐ a.m. ☐ p.m. to 1:00 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete (3/31 1 p.m. 4 p.m.)

Date of last inspection 3/16-20/89 Weather conditions Clear/Cool.

Acreage 2600 ☐ Permitted 125 ☐ Disturbed 12 ☐ Regraded 12 ☐ Seeded 125 ☐ Bonded

Enforcement Action NONE

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☒	☐	☐	☐
2. Signs and markers	☒	☐	☐	☐
3. Topsoil	☒	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☐
— Diversions	☒	☐	☐	☒
— Sediment ponds and impoundments	☒	☐	☐	☐
— Other sediment control measures	☒	☐	☐	☐
— Surface and groundwater monitoring	☒	☐	☐	☒
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☒	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. INA/015/004

Inspection Date 3/31 – 4/3/89

Please number comments to correspond with topics on previous page.

General Comments: The field inspection covered the first day, March 31. The records portion was completed 4/3.

Diversions: No changes on the diversions were noted in terms of meeting performance standards. All diversions were in compliance including those that were maintained last fall.

Sediment Ponds: Sediment pond did not contain any runoff. The large wind blown tree that had fallen in the sediment pond as covered in the previous report has been removed.

Water Monitoring: Five water stations required to be sampled by the operator. First quarter sample records were reviewed and no problems noted.

Annual Report: The operator by cover letter dated March 31, 1989 submitted his annual report to the Division.

Copy of report mailed to Beaver Creek Coal Co., Dave Guy. SLC For: OSM/Brain Smith; DOGM/Joe Helfrich

Copy of report ~~given to~~ filed Price Field Office

Inspector's signature Tim J. Chalmuck No. 26

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

4/5/89

DOGM/IR-2

an equal opportunity employer

11/86 001049