12-12-88 7085

0001

UTAH NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. INA/015/007

Inspection Date DEC. 5, 1988

Permittee/Operator Name CALIFORNIA PORTLAND CEMENT

Business Address 695 SOUTH RANCHO AVENUE

City COLTON State CA Zip 92324-0514

Mine HIDDEN VALLEY ☐ Surface ☒ Underground ☐ Other

County EMERY State UT

Company Official(s) NONE

State Official(s) BILL WAKMACK

Time of inspection 9 30 ☒ a.m. ☐ p.m. to 11 00 ☒ a.m. ☐ p.m. ☒ Partial ☐ Complete

Date of last inspection 11/7/88 Weather conditions CLEAR & FAIR

Acreage 960 ☒ Permitted 7 ☒ Disturbed 7 ☒ Regraded 7 ☒ Seeded 7 ☒ Bonded

Enforcement Action NONE

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☒	☐	☐	☒
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
a Stream channel diversions	☐	☐	☐	☐
b Diversions	☐	☐	☐	☐
c Sediment ponds and impoundments	☐	☐	☐	☐
d Other sediment control measures	☒	☐	☐	☒
e Surface and groundwater monitoring	☐	☐	☐	☐
f Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☒	☐	☐	☒
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. IN/015/007

Inspection Date 12/5/88

Please number comments to correspond with topics on previous page.

GENERAL: SNOW FROM PREVIOUS STORM ACTIVITY HAS MELTED, HOWEVER, SOME SMALL PATCHES WERE LINGERING ON THE SHADY, NORTH FACING SLOPES. IVIE CREEK WAS FLOWING & A THIN LAYER OF ICE (APPROX. 1") COVERED THE STREAM BED.

2. SIGNS & MARKERS: THE MINE I.D SIGN HAS BEEN SUBJECTED TO VANDALISM, 4 to 5 SHOTGUN BLASTS WERE DIRECTED AT THE SIGN PROBABLY BY AREA BIRD HUNTERS. ALTHOUGH STILL LEGIBLE, THE SIGN MIGHT REQUIRE REPLACEMENT IF INCIDENTS REOCCUR.

4d. OTHER SED CONTROLS: SILT FENCE INSTALLATION ON THE EASTERN SLOPE HAS BEEN COMPLETED. THE SILT FENCES REPLACE THE PREVIOUSLY USED ROCK CHECK DAMS WHICH HAD BECOME "COSMETIC".

Copy of report mailed to

Copy of report given to

Inspector's signature BW No.

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

an equal opportunity employer

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. INA/015/007

Inspection Date 12/5/88

Please number comments to correspond with topics on previous page.

13. REVEGETATION:

(1) THE ACCESS ROAD HAS BEEN SEEDED, COVERED WITH STRAW, & ALSO COVERED WITH NETTING. THE BARE AREA BELOW THE GATE HAS BEEN TREATED WITH LIME TO ENHANCE THE SOIL.

(2) THE NORTHERN SLOPE (ACROSS CHANNEL) HAS BEEN SEEDED & COVERED WITH STRAW. HOPEFULLY, A STRONG GROWTH WILL DEVELOP NEXT GROWING SEASON.

Copy of report mailed to JOE HELFRICH (DOGM); BRIAN SMITH (OSM) JOHN RAWLS (CPC), KARLA KNOOP (JBR)

Copy of report ~~given~~ FILED to PFO

Inspector's signature William A. Wermack 12/16/88 No. 30

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

an equal opportunity employer

7088

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. INA/015/007

Inspection Date DEC. 5, 1988

Permittee/Operator Name CALIFORNIA PORTLAND CEMENT

Business Address 695 SOUTH RANCHO AVENUE

City COLTON State CA Zip 92324-0514

Mine HIDDEN VALLEY ☐ Surface ☒ Underground ☐ Other

County EMERY State UT

Company Official(s) NONE

State Official(s) BILL WAGNACK

Time of Inspection 9 30 ☒ a.m. ☐ p.m. to 11 00 ☒ a.m. ☐ p.m. ☒ Partial ☐ Complete

Date of last inspection 11/7/88 Weather conditions CLEAR & FAIR

Acreage 960 ☒ Permitted 7 ☒ Disturbed 7 ☒ Regraded 7 ☒ Seeded 7 ☒ Bonded

Enforcement Action NONE

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☒	☐	☐	☒
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
a Stream channel diversions	☐	☐	☐	☐
b Diversions	☐	☐	☐	☐
c Sediment ponds and impoundments	☐	☐	☐	☐
d Other sediment control measures	☒	☐	☐	☒
e Surface and groundwater monitoring	☐	☐	☐	☐
f Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☒	☐	☐	☒
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
– Construction	☐	☐	☐	☐
– Drainage controls	☐	☐	☐	☐
– Surfacing	☐	☐	☐	☐
– Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. IUA/015/007

Inspection Date 12/15/88

Please number comments to correspond with topics on previous page.

GENERAL: SNOW FROM PREVIOUS STORM ACTIVITY HAS MELTED, HOWEVER, SOME SMALL PATCHES WERE LINGERING ON THE SHADY, NORTH FACING SLOPES. IVIE CREEK WAS FLOWING & A THIN LAYER OF ICE (APPROX. 1") COVERED THE STREAM BED.

2. SIGNS & MARKERS: THE MINE I.D. SIGN HAS BEEN SUBJECTED TO VANDALISM, 4 to 5 SHOTGUN BLASTS WERE DIRECTED AT THE SIGN PROBABLY BY AREA BIRD HUNTERS. ALTHOUGH STILL LEGIBLE, THE SIGN MIGHT REQUIRE REPLACEMENT IF INCIDENTS REOCCUR.

4d. OTHER SED CONTROLS: SILT FENCE INSTALLATION ON THE EASTERN SLOPE HAS BEEN COMPLETED. THE SILT FENCES REPLACE THE PREVIOUSLY USED ROCK CHECK DAMS WHICH HAD BECOME "COSMETIC".

Copy of report mailed to

Copy of report given to

Inspector's signature BW No.

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

an equal opportunity employer

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ~~TNA/015/007~~

Inspection Date 12/5/88

Please number comments to correspond with topics on previous page.

13. REVEGETATION:

(1) THE ACCESS ROAD HAS BEEN SEEDED, CAULKED WITH STRAW, & ALSO MULCHED WITH NETTING. THE BARE AREA BELOW THE GATE HAS BEEN TREATED WITH LIME TO ENHANCE THE SOIL.

(2) THE NORTHERN SLOPE (ACCESS CHANNEL) HAS BEEN SEEDED & CAULKED WITH STRAW. HOPEFULLY, A STRONG GROWTH WILL DEVELOP NEXT GROWING SEASON.

Copy of report mailed to JOE HELFRICH (DOGM); BRIAN SMITH (OSM) JOHN ROLLS (CPC); KARLA KNOOP (TBR)

Copy of report ~~given~~ FILED to PFO

Inspector's signature William A. Wermack 12/6/88 No. 30

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE