



STATE OF UTAH
NATURAL RESOURCES
Oil, Gas & Mining

0002

John

Norman H. Bangerter, Governor
Dee C. Hansen, Executive Director
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: November 7, 1988
10:00 a.m. - 12:00 p.m.

Permittee and/or Operators Name: California Portland Cement
Business Address: 695 South Rancho Avenue Colton, CA 92324-0514
Mine Name: Hidden Valley Permit Number: INA/015/007
Type of Mining Activity: Underground Surface Other
County: Emery State: Utah
Company Official(s): Karla Knoop (JBR Consultants)
State Official(s): Bill Warmack
Partial: Complete: Date of Last Inspection: October 24, 1988
Weather Conditions: Partly cloudy, breezy
Acreage: Permitted 960 Disturbed 7 Regraded 7 Seeded 7 Bonded 7
Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	(X)	()	()	(X)
2. SIGNS AND MARKERS	(X)	()	()	(X)
3. TOPSOIL	(X)	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	(X)	()	()	()
b. DIVERSIONS	(X)	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	()	()	(X)	()
d. OTHER SEDIMENT CONTROL MEASURES	(X)	()	()	(X)
e. SURFACE AND GROUNDWATER MONITORING	(X)	()	()	(X)
f. EFFLUENT LIMITATIONS	()	()	(X)	()
5. EXPLOSIVES	()	()	(X)	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	(X)	()
7. COAL PROCESSING WASTE	()	()	(X)	()
8. NONCOAL WASTE	()	()	(X)	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	(X)	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	(X)	()
11. CONTEMPORANEOUS RECLAMATION	(X)	()	()	()
12. BACKFILLING AND GRADING	(X)	()	()	()
13. REVEGETATION	(X)	()	()	(X)
14. SUBSIDENCE CONTROL	()	()	(X)	()
15. CESSATION OF OPERATIONS	()	()	(X)	()
16. ROADS				
a. CONSTRUCTION	(X)	()	()	()
b. DRAINAGE CONTROLS	(X)	()	()	()
c. SURFACING	()	()	(X)	()
d. MAINTENANCE	(X)	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	(X)	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	(X)	()

INSPECTION REPORT
(continuation sheet)

Page 2 of 3

PERMIT NUMBER: ACT/015/007

DATE OF INSPECTION Nov. 7, 1988

(Comments are Numbered to Correspond with Topics Listed Above)

GENERAL COMMENTS:

The undersigned inspector was accompanied by Karla Knoop (JBR Consultants) during this complete inspection. Revegetation and maintenance work was being completed throughout the site.

1. PERMITS:

CALMAT received a final approval of PAP Amendment on June 9, 1988. No further amendments or approvals were pending at this time.

2. SIGNS AND MARKERS:

The mine I.D. sign has been reinstalled on the post once again, and has been secured in such a manner to prevent future problems.

4d. OTHER SEDIMENT CONTROL MEASURES:

1. Silt fences were being installed on the eastern slope where rock check dams had been previously built.
2. The existing silt fences were observed and found in good repair. Some minor enhancement work will be done as necessary before work is terminated.
3. In a few general areas, some minor rilling has occurred from previous storms; straw and/or rock will be placed to prevent future problems from developing.

4e. SURFACE AND GROUND WATER MONITORING:

According to Karla, September water samples were taken during the first part of the quarter. At this time, field and laboratory results are not available and will be referenced when received.

13. REVEGETATION:

1. The main access road has been ripped along its entire length and will be reseeded. A bare area that has been referenced in prior reports will be treated with lime to alleviate the possible acidity problem. As the road is seeded, straw and netting will be placed to ensure proper growth.

INSPECTION REPORT
(continuation sheet)

Page 3 of 3

PERMIT NUMBER: ACT/015/007

DATE OF INSPECTION Nov. 7, 1988

(Comments are Numbered to Correspond with Topics Listed Above)

2. The northern slope was being reseeded and covered with straw in hopes of establishing strong vegetative growth next year.

NOTE: All areas that have been reseeded were broadcasted and hand raked if necessary.

Copy of this Report:

Mailed to: John Rains, California Portland Cement

Mailed to SLC for: Brian Smith, OSM; Joe Helfrich, DOGM

Filed to: PFO

Inspectors Signature and Number: William A. Warmack #30 Date: Nov. 8, 1988

William A. Warmack 11/8/88