



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangarter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

John

INSPECTION DATE & TIME: July 6, 1988
9:00-9:45 a.m.

Permittee and/or Operators Name: California Portland Cement
Business Address: 695 South Rancho Avenue Colton, Calif. 92324-0514
Mine Name: Hidden Valley Permit Number: [REDACTED]
Type of Mining Activity: Underground Surface Other
County: Emery State: Utah
Company Official(s): None
State Official(s): Bill Warmack and Tom Munson
Partial: Complete: Date of Last Inspection: June 21, 1988
Weather Conditions: Clear and warm
Acreage: Permitted 960 Disturbed 7 Regraded 7 Seeded 7 Bonded 7
Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	(X)	()	()	()
2. SIGNS AND MARKERS	(X)	()	()	(X)
3. TOPSOIL	()	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	(X)	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	()	()	()	()
d. OTHER SEDIMENT CONTROL MEASURES	(X)	()	()	(X)
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	(X)	()
5. EXPLOSIVES	()	()	(X)	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	(X)	()
7. COAL PROCESSING WASTE	()	()	(X)	()
8. NONCOAL WASTE	()	()	(X)	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	(X)	()
10. SLIDES AND OTHER DAMAGE	()	()	(X)	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	(X)	()	()	()
14. SUBSIDENCE CONTROL	()	()	(X)	()
15. CESSATION OF OPERATIONS	()	()	(X)	()
16. ROADS				
a. CONSTRUCTION	()	()	(X)	()
b. DRAINAGE CONTROLS	(X)	()	()	()
c. SURFACING	()	()	(X)	()
d. MAINTENANCE	()	()	(X)	()
17. OTHER TRANSPORTATION FACILITIES	()	()	(X)	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	(X)	()

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/007

DATE OF INSPECTION July 6, 1988

(Comments are Numbered to Correspond with Topics Listed Above)

GENERAL COMMENTS:

Ground conditions were dry with no evidence of measurable precipitation. No erosion problems were encountered.

2. SIGNS AND MARKERS:

The permit sign needs to be installed back on its post.

4d. OTHER SEDIMENT CONTROL MEASURES:

All silt fences were up and functioning properly.

13. REVEGETATION:

Considerable amount of plant growth was observed especially in the "roughed-out" areas. The seeded areas show signs of perennial vegetation establishment; however, there has been a widespread invasion of halogeton within the disturbed areas. The density of halogeton varies. It is most dense in those areas where perennial vegetation is sparse. An evaluation should be made before fall to determine what areas, if any, should be reseeded.

Copy of this Report:

Mailed to: John Rains, California Portland Cement

Mailed to SLC for: Brian Smith, OSM; Joe Helfrich and Tom Munson, DOGM

Filed to: PFO

Inspectors Signature and Number: William A. Warmack #30 Date: July 13, 1988