70085 5-25-89

0010

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

gd RVS

inspection report

Permit No. INA/015/007

Inspection Date April 19, 1989

Permittee/Operator Name California Portland Cement

Business Address 695 South Rancho Avenue

City Colton State CA Zip 92324-0574

Mine Hidden Valley ☐ Surface ☒ Underground ☐ Other

County Emery State UT

Company Official(s) None

State Official(s) Bill Wagnack & Lane Owen (OSM)

Time of inspection 2:00 ☐ a.m. ☒ p.m. to 4:00 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete

Date of last inspection April 6, 1989 Weather conditions warm

Acreage 960 ☒ Permitted 7 ☒ Disturbed 7 ☒ Regraded 7 ☒ Seeded 7 ☒ Bonded

Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☐	☐	☐	☐
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
a Stream channel diversions	☐	☐	☐	☐
b Diversions	☐	☐	☐	☐
c Sediment ponds and impoundments	☐	☐	☐	☐
d Other sediment control measures	☒	☐	☐	☒
e Surface and groundwater monitoring	☐	☐	☐	☐
f Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☒	☐	☐	☒
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. INA/015/007

Inspection Date 4/19/89

Please number comments to correspond with topics on previous page.

GENERAL: THE UNDERSIGNED INSPECTOR WAS ACCOMPANIED BY DARON HADDOCK (DOGM) & RAYE OKELL (OSM) DURING THIS INSPECTION. NO ENFORCEMENT ACTIONS WERE TAKEN ON THE PART OF DOGM OR BY MR. OKELL.

THE SITE WAS ACCESSED ALONG THE RECLAIMED ROAD WHICH HAD BEEN RIPPED & SEEDED LAST FALL ('88). NO SIGNS OF NEW VEGETATION (DESIRABLES) WERE EVIDENT AT THIS TIME.

BOTH OF THE A & B SEAM FILL SLOPES WERE RESEEDED & THE ASSOCIATED DRAINAGES ~~[illegible]~~ FOR EACH. ALL OF THE SILT FENCES ON SITE WERE INTACT & APPEARED TO BE FUNCTIONAL.

THE SITE WAS DRY WITH NO SIGNS OF RECENT PRECIPITATION PRESENT.

Copy of report mailed to SLC FOR: JOE HELFRICH (DOGM), BRIAN SMITH (OSM)
TO: JOHN RAINS (CPC), RANDY KNOOP (J&R)

Copy of report given to PFO

Inspector's signature William A. Wermack No. 30

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

an equal opportunity employer