0001

UTAH NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. ~~[illegible]~~ 007

Inspection Date 12/13/90

Permittee/Operator Name Cal Mat Company

Business Address 1801 University Dr.

City Phoenix State AZ Zip 85034

Mine Hidden Valley ☐ Surface ☒ Underground ☐ Other

County Emery State UT

Company Official(s) Karla Lamp (JBR)

State Official(s) Susan White Jeff Bingo (OSM)

Time of inspection 2:00 ☐ a.m. ☒ p.m. to 4:00 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete

Date of last inspection 12/7/90 Weather conditions ~~[illegible]~~ cloudy and cold

Acreage 950 ☒ Permitted 7 ☐ Disturbed 7 ☐ Regraded 7 ☐ Seeded 7 ☒ Bonded

Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☒	☐	☐	☒
2. Signs and markers	☒	☐	☐	☒
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
a. Stream channel diversions	☐	☐	☐	☐
b. Diversions	☐	☐	☐	☐
c. Sediment ponds and impoundments	☐	☐	☐	☐
d. Other sediment control measures	☒	☐	☐	☒
e. Surface and groundwater monitoring	☐	☐	☐	☐
f. Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☒	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
– Construction	☐	☐	☐	☐
– Drainage controls	☐	☐	☐	☐
– Surfacing	☐	☐	☐	☐
– Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. C/014/015/007

Inspection Date 12/13/90

Please number comments to correspond with topics on previous page.

In general the site looked very good. No precipitation had occured on site since the October storms. All suggested maintance items from previous inspections had been taken care of.

2. The permit sign at the entrance to the property has been updated with the owners new address.

1. Phase I bond release was effective 7/17/88.

4.d. While fully functional some maintance is required on the silt fence near the B seam.

Questions addressed by OSM were ASCA, and the varriance which allowed AOC on the road and B seam highwall.

Copy of report mailed to John Kathman (OSM), Lee Edmonson (Cal Mat), and Karla Knoop (JBR)

Copy of report given to Joe Helfrich

Inspector's signature Susan M. White No. 35

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

an equal opportunity employer