0010

UTAH NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

Page 1 of ___

Jd pge

inspection report

Permit No. ACT/015/007

Inspection Date 7/11/91

Permittee/Operator Name Cal Mat Co.

Business Address 1801 University Drive,

City Phoenix State AZ Zip 85034

Mine HIDDEN VALLEY ☒ Surface ☐ Underground ☐ Other

County EMERY State UTAH

Company Official(s) KARLA KNOOP (FBR Consultant Group Inc.)

State Official(s) HENRY SAUER

Time of inspection 11:00 ☒ a.m. ☐ p.m. to 12:15 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete

Date of last inspection 6/12/91 Weather conditions Clear and Hot

Acreage 950.0 ☒ Permitted 7.0 ☒ Disturbed 7.0 ☒ Regraded 7.0 ☒ Seeded 7.0 ☒ Bonded

Enforcement Action NONE

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☒	☐	☐	☒
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
– Stream channel diversions	☐	☐	☐	☐
– Diversions	☐	☐	☐	☐
– Sediment ponds and impoundments	☐	☐	☐	☐
– Other sediment control measures	☒	☐	☐	☒
– Surface and groundwater monitoring	☐	☐	☐	☐
– Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☒	☐	☐	☒
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
– Construction	☐	☐	☐	☐
– Drainage controls	☐	☐	☐	☐
– Surfacing	☐	☐	☐	☐
– Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/007

Inspection Date 7/12/91

Please number comments to correspond with topics on previous page.

2) SIGNS AND MARKERS -
The new improved mine identification sign is in place and clearly visible. Cal Mat Co. has opted to indicate the address of the companies general inquiry office. The address is as follows: HIDDEN VALLEY COAL CO., HIDDEN VALLEY MINE, P.O. BOX 2950 Terminal Annex, Los Angeles, California 90051 PHONE: 1-800-225-6280.

4D) Hydrologic Balance - Other Sediment Control Measures:
Karla Knoop informed me that all the silt fences will be replace within a month. Additionally the suspected piping area will be investigated at that time.

13) Revegetation - The Elymus species and Agropyron cristatum individuals have set seed. Ceratoides lanata is in an excess and small sprigs of what appears to be an Agropyron species have recently emerged.
In general the area is drying up. The Kochia species are showing signs of moisture stress.

Copy of report mailed to Lee Edmonson (CalMat), Karla Knoop (JBR) John Kathman (OSM)

Copy of report given to Joe Helfrich (DOGM)

Inspector's signature Henry Sauer No. 32

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE