0012

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

Get copy

inspection report

Permit No. ACT/015/007

Inspection Date 5/7/91

Permittee/Operator Name Cal Mat Co.

Business Address 1801 University Drive

City Phoenix State Ariz Zip 85034

Mine Hidden Valley ☐ Surface ☒ Underground ☐ Other

County Emery State Ut

Company Official(s) None

State Official(s) Bill Malencik, Hugh Klein

Time of inspection 1:00 ☐ a.m. ☒ p.m. to 4:00 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete

Date of last inspection 4/26/91 Weather conditions Clear/Windy

Acreage 950 ☐ Permitted 7 ☐ Disturbed 7 ☐ Regraded 7 ☐ Seeded 7 ☐ Bonded

Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☒	☐	☐	☐
3. Topsoil	☐	☐	☒	☐
4. Hydrologic balance				
— Stream channel diversions	☒	☐	☐	☐
— Diversions	☒	☐	☐	☐
— Sediment ponds and impoundments	☐	☐	☒	☐
— Other sediment control measures	☒	☐	☐	☒
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☒	☐
7. Coal processing waste	☐	☐	☒	☐
8. Noncoal waste	☒	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☒	☐	☐	☒
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/007

Inspection Date 5/7/91

Please number comments to correspond with topics on previous page.

General Comments. On site conditions were substantiality the same as covered in the previous inspection dated 4/20/91. The mine site was dry and showed no evidence of rain or runoff.

Followup On Previous Inspections. Division on May 6, 1991 received W. Hard Tiptons letter on TDL 91-02-370-002TV1 relative to the elimination of highwalls. The letter indicates and orders a federal inspection.

Other Sediment Control. Silt fences and the erosion matting all were checked and no problems noted.

Vegetation. The seeding project showed minimal response to vegetation establishment. Saltbush plants were observed along the reclaimed road. Grass plants are hard to find except in moisture depressions

Copy of report mailed to Cal Mat / Lee Edmonson; OSM / Brian Smith; DOGM / Joe Helfrich

Copy of report ~~given to~~ filed RFO

Inspector's signature [signature] No. 26

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

5/10/91

DOGM/IR-2

an equal opportunity employer

11/86 001049