0015

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. [redacted]

Inspection Date 2/8/91

Permittee/Operator Name Cal Mat Co.

Business Address 1801 University Dr.

City Phoenix State Az Zip 85034

Mine Hidden Valley ☐ Surface ☒ Underground ☐ Other

County Emery State Ut

Company Official(s) None

State Official(s) Bill Malencik

Time of inspection 1:__ ☐ a.m. ☒ p.m. to 4:00 ☐ a.m. ☒ p.m. ☐ Partial ☒ Complete

Date of last inspection 1/10/91 Weather conditions Clear/Dry/Pleasant Temp.

Acreage 950 ☐ Permitted 7 ☐ Disturbed 7 ☐ Regraded 7 ☐ Seeded 7 ☐ Bonded

Enforcement Action

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☒	☐	☐	☐
2. Signs and markers	☒	☐	☐	☒
3. Topsoil	☐	☐	☒	☐
4. Hydrologic balance				
— Stream channel diversions	☒	☐	☐	☐
— Diversions	☒	☐	☐	☐
— Sediment ponds and impoundments	☐	☐	☒	☐
— Other sediment control measures	☒	☐	☐	☒
— Surface and groundwater monitoring	☒	☐	☐	☐
— Effluent limitations	☒	☐	☐	☒
5. Explosives	☐	☐	☒	☐
6. Development waste and spoil disposal	☐	☐	☒	☐
7. Coal processing waste	☐	☐	☒	☐
8. Noncoal waste	☒	☐	☐	☒
9. Protection of fish, wildlife, and related environmental values	☒	☐	☐	☐
10. Slides and other damage	☒	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☒	☐
12. Backfilling and grading	☒	☐	☐	☒
13. Revegetation	☒	☐	☐	☒
14. Subsidence control	☐	☐	☒	☐
15. Cessation of operations	☐	☐	☒	☐
16. Roads				
— Construction	☒	☐	☐	☐
— Drainage controls	☒	☐	☐	☐
— Surfacing	☒	☐	☐	☐
— Maintenance	☒	☐	☐	☐
17. Other transportation facilities	☐	☐	☒	☐
18. Support facilities and utility installations	☐	☐	☒	☐

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/007

Inspection Date 2/8/91

Please number comments to correspond with topics on previous page.

General Comments. This complete inspection was performed in coordination with Ms. Karla Knoop, D.B.E. the designated field representative (Calmat). She advised me that a Feb field trip would be made wherein she would (1) upgrade the I.D. sign and (2) review the fence locations as depicted on the Dec. 1990 Reclamation map/plate III, revised 12/18/90.

Field conditions as related to on site environmental control measures have not change since the last inspections as described by Ms. White and the previous oversight inspection completed in December 1990.

Pending Enforcement Items. As a result of the December inspection, OSM on 1/4/91 issued TDN 91-02-246-1 TV 2 on two issues.

*(1) Failure to demonstrate alternative sediment control areas to meet effluent standards, and

*(2) Failure to reshape cut & fill slopes to original contour.

Diversions All diversions appeared stable without significant erosion or sediment deposition which would limit their effectiveness to convey runoff.

Copy of report mailed to _____

Copy of report given to _____

Inspector's signature _____ No. _____

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

an equal opportunity employer

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/007

Inspection Date 2/8/91

Please number comments to correspond with topics on previous page.

Noncoal Waste. No cans or garbage was observed at the mine site including at the end of the blacktop road adjacent to the permit area.
Revegetation. The vegetation was still in a dormant stage. No significant changes could be detected over and above what had previously been reported and/or observed.

Copy of report mailed to Lee Edmonson (Calmat), Karla Knoop (JBR), John Kathman (OSM)

Copy of report given to Joe Helfrich (DOGM)

Inspector's signature Jim J. Smalenik No. 26

2/11/91

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

DOGM/IR-2

an equal opportunity employer

11/86 001049