0053

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

REC

FEB 19 1992

DIVISION OF OIL
GAS & MINING PRICE UTAH

inspection report

Permit No. ACT/015/007

Inspection Date 5 January 1992

Permittee/Operator Name Cal Mat Company

Business Address 1801 University Drive

City Phoenix State Arizona Zip 85034

Mine Hidden Valley ☐ Surface ☒ Underground ☐ Other

County Emery State Utah

Company Official(s) None

State Official(s) Jess Kelley

Time of inspection 11:00 ☒ a.m. ☐ p.m. to 12:30 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete

Date of last inspection 16 December 1991 Weather conditions Cool and sunny

Acreage 950 ☐ Permitted 7 ☐ Disturbed 7 ☐ Regraded 7 ☐ Seeded 7 ☐ Bonded

Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☐	☐	☐	☐
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
a Stream channel diversions	☐	☐	☐	☐
b Diversions	☒	☐	☐	☒
c Sediment ponds and impoundments	☐	☐	☐	☐
d Other sediment control measures	☐	☐	☐	☐
e Surface and groundwater monitoring	☐	☐	☐	☐
f Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☒	☐	☐	☒
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
a Construction	☐	☐	☐	☐
b Drainage controls	☐	☐	☐	☐
c Surfacing	☐	☐	☐	☐
d Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☒	☐	☐	☒
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/007

Inspection Date 5 ~~January~~ February 1992

Please number comments to correspond with topics on previous page.

4. HYDROLOGIC BALANCE

(b) Diversions-- All diversions are in good repair and free of debris.

13. REVEGETATION

The entire site is damp from melted snow. Vegetation is sparse, especially on the seam fills, but it seems to have gotten a moderate start.

NOV N91-26-8-2 of 2, which was written November 22, 1991, deals with the Permittee's failure to seed and vegetate the pad outslope adjacent to Ivie Creek.

17. OTHER TRANSPORTATION FACILITIES

For this inspection, the site was accessed on foot by way of the prelaw access road along Ivie Creek. Happily, this road, which was used very little, is completely covered with natural vegetation and has been obliterated by the elements to the point that it is, for the most part, almost invisible against the surrounding topography.

Copy of report mailed to Lee Edmonson/CalMat; Karla Knoop/JBR; Bernie Freeman/OSM

Copy of report given to Joe Helfrich/DOGM; Price Field Office/DOGM

Inspector's signature Gene W. Kelley No. 34

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

an equal opportunity employer