



State of Utah
 DEPARTMENT OF NATURAL RESOURCES
 DIVISION OF OIL, GAS AND MINING

INSPECTION REPORT

page 1 of 1

Michael O. Leavitt
 Governor
 Ted Stewart
 Executive Director
 James W. Carter
 Division Director

355 West North Temple
 3 Triad Center, Suite 350
 Salt Lake City, Utah 84180-1203
 801-538-5340
 801-358-3940 (Fax)
 801-538-5319 (TDD)

Partial: X Complete: Exploration:
 Inspection Date & Time: 4/14/93 3:00pm to 5:00pm
 Date of Last Inspection: 3/3/93

Mine Name: Hidden Valley County: Emery Permit Number: ACT/015/007
 Permittee and/or Operator's Name: CALMAT Co. (Hidden Valley Coal Company)
 Business Address: 1801 University Drive, Phoenix, Arizona 85034
 Type of Mining Activity: Underground X Surface Prep. Plant Other
 State Official(s): Tom Munson
 Company Official(s): None
 Federal Official(s): None
 Weather Conditions: Clear and Cold
 Existing Acreage: Permitted-950 Disturbed-6 Regraded-7 Seeded-<6 Bonded-7
 Increased/Decreased: Permitted- Disturbed- Regraded- Seeded- Bonded-
 Status: Exploration/ Active/ Inactive/ Temporary Cessation/ Bond Forfeiture
 Reclamation (X Phase I/ Phase II/ Final Bond Release/ Liability Year)

REVIEW OF PERMIT PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

	EVALUATED	N/A	COMMENTS	NOV/ENF
1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. SIGNS AND MARKERS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. TOPSOIL	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. HYDROLOGIC BALANCE:				
a. DIVERSIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
b. SEDIMENT PONDS AND IMPOUNDMENTS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
c. OTHER SEDIMENT CONTROL MEASURES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
d. WATER MONITORING	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
e. EFFLUENT LIMITATIONS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. EXPLOSIVES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. NONCOAL WASTE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
10. SLIDES AND OTHER DAMAGE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. CONTEMPORANEOUS RECLAMATION	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. BACKFILLING AND GRADING	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. REVEGETATION	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
14. SUBSIDENCE CONTROL	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. CESSATION OF OPERATIONS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16. ROADS:				
a. CONSTRUCTION/MAINTENANCE/SURFACING	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
b. DRAINAGE CONTROLS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. OTHER TRANSPORTATION FACILITIES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. SUPPORT FACILITIES/UTILITY INSTALLATIONS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
19. AVS CHECK (4th Quarter-April, May, June) _____ (date)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. AIR QUALITY PERMIT	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. BONDING & INSURANCE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>



INSPECTION REPORT

pgl

(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/007 DATE OF INSPECTION: 4/14/93

(Comments are Numbered to Correspond with Topics Listed Above)

Site Conditions -

The site had no snow on it and the ground was not frozen.

1.) Permits - The operator's permits are current and in effect. N.O.V.'s 91-26-8-2; 2 of 2, and 91-26-8-2; 1 of 2 remain unabated and are still being decided by the courts.

4a.) The main stream channel diversion is in good repair and has not seen any significant events this year.

4c.) Sediment Control Measures - All silt fences were operational and in good repair. It appeared as if some maintenance had occurred on the road to areas around several of the water bars. Erosion is becoming evident on the south end of the "A" Seam pad.

9.) Wildlife - Elk usage continues to occur on site and was evident throughout the entire site.

13.) Revegetation - No revegetation has been carried out since the last inspection.

Copy of this Report:

Mailed to: Bernie Freeman (OSM), Lee Edmonson (CALMAT), Karla Knoop (JBR)
Given to: Joe Helfrich (DOGM)

Inspector's Signature: *Tom Muns* # 25 4/28/92