0022

UTAH NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. [redacted]007

Inspection Date 3/3/93

Permittee/Operator Name Hidden Valley Coal Company

Business Address 1801 University Drive

City Phoenix State Arizona Zip 85034

Mine Hidden Valley ☐ Surface ☒ Underground ☐ Other

County Emery State Ut

Company Official(s) None (Conversed with Karla Knoop)

State Official(s) Bill Malencik

Time of inspection 1:30 ☐ a.m. ☒ p.m. to 4:30 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete

Date of last inspection 1/26/93 Weather conditions Clear/Temp 50°'s

Acreage 950 ☐ Permitted 6' ~~7~~ ☐ Disturbed 6' ~~7~~ ☐ Regraded less than 6' ~~7~~ ☐ Seeded 7 ~~7~~ ☐ Bonded

Enforcement Action None as a result of the instant inspection
Violations noted below are still outstanding.

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
NOV 91-26-8-2 2-2 Still Unabated — 2. Signs and markers	☒	☒	☐	☒
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☐
— Diversions	☒	☒	☐	☒
NOV 91-26-8-2 1 of 2 Still Unabated — Sediment ponds and impoundments	☐	☐	☐	☐
— Other sediment control measures	☒	☒	☐	☒
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☒	☐	☐	☒
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation NOV 91-26-8-2 2 of 2	☒	☒	☐	☒
14. Subsidence control Still Unabated.	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

* Order by D.R. Nielson concluded the disturbed area is 6.1 acres and not all of the disturbed area has been seeded as defined in NOV 91-26-8-2; 2 of 2.

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. Act/015/007

Inspection Date 3/3/93

Please number comments to correspond with topics on previous page.

General Comments. At the end of the paved road and next to the mine ID sign, twelve inches of snow is still lying on the ground. The road to the gate was snow covered. The road below the gate had patches of snow. The road outslope was clear of snow, but somewhat muddy with the afternoon favorable temperatures.

Outstanding Violations. Violations noted on page 1 of this report have not been abated. No on the ground corrective action has taken place. Sto my understanding the permittee is continuing to pursue this matter in the courts.

Signs & Markers. The I.D. Sign is in place, but continues to receive bullet holes from unknown individuals. Disturbed markers have not been installed to mark all the disturbed areas ie, road outslope A&B pad contiguous to Dvie Creek (NOV 91-26-8-2; 2 of 2).

Diversions/Other Sediment Control. Erosion on the three gullies continues unabated (NOV 91-26-8-2; 1 of 2).

Revegetation. Seeding of the road outslopes and the A&B pad outslopes contiguous to Dvie Creek has not been

Copy of report mailed to

Copy of report given to

Inspector's signature No.

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. Act/015/007

Inspection Date 3/3/93

Please number comments to correspond with topics on previous page.

Completed. Also, the road has not been reseeded as required in NOV 91-26-8-2; 2 of 2.

Wildlife. Observed eleven elk on the B seam. Didnt see any elk tracks above the gate. It appears the elk are staying next to Ivie Creek and are grazing along the creek bottom.

Copy of report mailed to HVCC/Lee Edmonson; OSM/Brian Smith; DOGM/Joe Helfrich

Copy of report given to

Inspector's signature Tom J. Malmnick No. 26

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

DOGM/IR-2 COPY 3/4/93 TOM MUNSON

an equal opportunity employer

11/86 001049