



gh

- Partial
- Complete
- Exploration

Inspection Date: April 1, 1994
 Time: 10:00 am pm to 3:30 am pm
 Date of Last Inspection: March 24, 1994

Mine Name: Hidden Valley County: Emery Permit Number: Act/015/007
 Permittee and/or Operator's Name: Calmat Co.
 Business Address: 1801 University Drive, Phoenix, Arizona 85034
 Type of Mining Activity: Underground Surface Prep. Plant Other
 State Official(s): Bill Malencik
 Company Official(s): None
 Federal Official(s): None

Weather Conditions: Cloudy, Windy, & Cold
 Existing Acreage: Permitted- 950 Disturbed- 7 Regraded- 7 Seeded See the 7 Bonded- 7

Increased/Decreased: Permitted- _____ Disturbed- _____ Regraded- _____ Seeded- _____ Bonded- _____

Status: Exploration / Active / Inactive / Temporary Cessation / Bond Forfeiture
 Reclamation (Phase I / Phase II / Final Bond Release / Liability _____ Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

| | EVALUATED | N/A | COMMENTS | NOV/ENF |
|--|-------------------------------------|--------------------------|-------------------------------------|--------------------------|
| 1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2. SIGNS AND MARKERS | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. TOPSOIL | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 4. HYDROLOGIC BALANCE: | | | | |
| a. DIVERSIONS | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| b. SEDIMENT PONDS AND IMPOUNDMENTS | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| c. OTHER SEDIMENT CONTROL MEASURES | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| d. WATER MONITORING | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| e. EFFLUENT LIMITATIONS | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 5. EXPLOSIVES | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 8. NONCOAL WASTE | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 10. SLIDES AND OTHER DAMAGE | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 11. CONTEMPORANEOUS RECLAMATION | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 12. BACKFILLING AND GRADING | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 13. REVEGETATION | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 14. SUBSIDENCE CONTROL | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 15. CESSATION OF OPERATIONS | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 16. ROADS: | | | | |
| a. CONSTRUCTION/MAINTENANCE/SURFACING | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| b. DRAINAGE CONTROLS | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 17. OTHER TRANSPORTATION FACILITIES | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 18. SUPPORT FACILITIES/UTILITY INSTALLATIONS | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 19. AVS CHECK (4th Quarter-April, May, June) _____ (date) | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 20. AIR QUALITY PERMIT | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 21. BONDING & INSURANCE | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 22. <u>Explosatory Wells/Drill Holes</u> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

inspection report

INSPECTION REPORT COMMENTS

Permit No. Act 015/007

Inspection Date _____

Please number comments to correspond with topics on previous page.

General Comment. The purpose of this inspection was to observe exploratory drill holes. These were sealed in 1993.

Also did a routine followup on the road that has been reclaimed relating to the public vehicle encroachment in these areas.

Exploratory Drill Holes: Observed drill holes 4, 5 & 6 and conditions are the same as reported in the 6/8/93 inspection report. All the aforementioned drill holes have been effectively sealed as required in the Division approved plan.

Road: Observed metal fence posts that supplement previous barriers to discourage and prevent unknown parties from driving over reclaimed areas. Some signing pointing out the area has been reclaimed and requesting the public to aid in plant establishment by not driving vehicles over the reclaimed area. Perhaps a vehicle logo with a line through it and verbage reclaimed and seeded area.

Copy of report mailed to Calmet/hee Edmanson, OSM/Marcia Petta; Davee Joe Helbrich

Copy of report given to DFO

Inspector's signature [Signature] No. 26

WHITE - DOGM YELLOW - OSM PINK - PERMITTEE/OPERATOR GOLDENROD - NOV FILE