



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

INSPECTION REPORT

Michael O. Leavitt
Governor
Ted Stewart
Executive Director
James W. Carter
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340
801-359-3940 (Fax)
801-538-5319 (TDD)

Partial: X Complete: Exploration:
Inspection Date & Time: 1/26/94 12 to 1:30
Date of Last Inspection: 12/2/93

Mine Name: Hidden Valley County: Emery Permit Number: ACT/015/007
Permittee and/or Operator's Name: CALMAT Co. (Hidden Valley Coal Company)
Business Address: 1801 University Drive, Phoenix, Arizona 85034
Type of Mining Activity: Underground X Surface Prep. Plant Other
State Official(s): Susan White
Company Official(s): Karla Knoop
Federal Official(s): None

Weather Conditions: Fair, windy and cold
Existing Acreage: Permitted-950 Disturbed-7 Regraded-7 Seeded-7 Bonded-7
Increased/Decreased: Permitted- Disturbed- Regraded- Seeded- Bonded-
Status: Exploration/ Active/ Inactive/ Temporary Cessation/ Bond Forfeiture
Reclamation ( X Phase I/ Phase II/ Final Bond Release/ Liability Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

Table with 5 columns: Item, EVALUATED, N/A, COMMENTS, NOV/ENF. Rows include items like PERMITS, CHANGE, TRANSFER, RENEWAL, SALE; SIGNS AND MARKERS; TOPSOIL; HYDROLOGIC BALANCE; EXPLOSIVES; DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES; COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS; NONCOAL WASTE; PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES; SLIDES AND OTHER DAMAGE; CONTEMPORANEOUS RECLAMATION; BACKFILLING AND GRADING; REVEGETATION; SUBSIDENCE CONTROL; CESSATION OF OPERATIONS; ROADS; CONSTRUCTION/MAINTENANCE/SURFACING; DRAINAGE CONTROLS; OTHER TRANSPORTATION FACILITIES; SUPPORT FACILITIES/UTILITY INSTALLATIONS; AVS CHECK; AIR QUALITY PERMIT; BONDING & INSURANCE.

## INSPECTION REPORT

(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/007

DATE OF INSPECTION: 1/26/94

(Comments are Numbered to Correspond with Topics Listed Above)

### 12. BACKFILLING AND GRADING

Metal fence posts were placed across the reclaimed road width to prevent vehicle access. The operator has committed to monitor the closure of the two track and natural colonization of vegetation. In the fall if natural recolonization has not occurred then the area will be revegetated.

### 13. REVEGETATION

The operator's representative stated that they had remeasured the reference area and vegetative cover was approximately 16 percent. The site is well below the standard of 16 percent perennial cover.

Evidence of erosion is still apparent on site.

Copy of this Report:

Mailed to: Bernie Freeman (OSM), Lee Edmonson (CALMAT)

Given to: Joe Helfrich (DOGM)

Inspector's Signature: *ASusan M. White* #35 Date: 1/31/94