STATE OF UTAH
NATURAL RESOURCES
Division of Oil, Gas & Mining
3 Triad Center · Suite 350 · Salt Lake City, UT 84180-1203 · (801) 538-5340

inspection report

☐ Partial
☑ Complete
☐ Exploration

Inspection Date: April 20, 1995
Time: 7 : 30 ☑am ☐pm to 2 : 00 ☐am ☑pm
Date of Last Inspection: 3/28/95

Mine Name: Hidden Valley. County: Emery Permit Number: Act 015/007
Permittee and/or Operator's Name: CalMat Co.
Business Address: 1801 University Drive, Phoenix, Arizona 85034
Type of Mining Activity: ☑ Underground ☐ Surface ☐ Prep. Plant ☐ Other
State Officials(s): Bill Malencik
Company Official(s): None
Federal Official(s): None
Weather Conditions: Cold/Windy/Reclaimed mine site contained good moisture
Existing Acreage: Permitted-950 Disturbed-7 Regraded-___ Seeded-___ Bonded-7
Increased/Decreased: Permitted-___ Disturbed-___ Regraded-___ Seeded-___ Bonded-___
Status: ☐ Exploration / ☐ Active / ☑ Inactive / ☐ Temporary Cessation / ☐ Bond Forfeiture
☐ Reclamation (☑ Phase I / ☐ Phase II / ☐ Final Bond Release / ☐ Liability 1996 Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions
1. Substantiate the elements on this inspection by checking the appropriate performance standard.
   a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
   b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	EVALUATED	N/A	COMMENTS	NOV/ENF
1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	☑	☐	☐	☐
2. SIGNS AND MARKERS	☑	☐	☐	☐
3. TOPSOIL	☐	☑	☐	☐
4. HYDROLOGIC BALANCE:				
a. DIVERSIONS	☑	☐	☐	☐
b. SEDIMENT PONDS AND IMPOUNDMENTS	☐	☑	☐	☐
c. OTHER SEDIMENT CONTROL MEASURES	☑	☐	☑	☐
d. WATER MONITORING	☑	☐	☐	☐
e. EFFLUENT LIMITATIONS	☑	☐	☐	☐
5. EXPLOSIVES	☐	☑	☐	☐
6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	☐	☑	☐	☐
7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	☐	☑	☐	☐
8. NONCOAL WASTE	☑	☐	☐	☐
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	☑	☐	☑	☐
10. SLIDES AND OTHER DAMAGE	☑	☐	☐	☐
11. CONTEMPORANEOUS RECLAMATION	☐	☑	☐	☐
12. BACKFILLING AND GRADING	☑	☐	☐	☐
13. REVEGETATION	☑	☐	☑	☐
14. SUBSIDENCE CONTROL	☐	☑	☐	☐
15. CESSATION OF OPERATIONS	☐	☑	☐	☐
16. ROADS:				
a. CONSTRUCTION/MAINTENANCE/SURFACING	☐	☐	☐	☐
b. DRAINAGE CONTROLS	☐	☐	☐	☐
17. OTHER TRANSPORTATION FACILITIES	☐	☑	☐	☐
18. SUPPORT FACILITIES/UTILITY INSTALLATIONS	☑	☐	☑	☐
19. AVS CHECK (4th Quarter-April, May, June) 4/20/95 (date)	☑	☐	☐	☐
20. AIR QUALITY PERMIT	☐	☐	☐	☐
21. BONDING & INSURANCE	☑	☐	☐	☐
Progress Report	☑		☑	

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. Act 015/017

Inspection Date 4/20/95

Please number comments to correspond with topics on previous page.

General Comments This complete inspection included a records review and a mine site visit

The records portion of this inspection was completed which include a review of the internal records. All were in order.

Was planning to visit the reclaimed mine site on 4/19/95 but delayed it a day because of adverse weather. It snowed 4" at Price and the storm was centered the previous day in "SE Utah"

Signs and Markers were observed. The I.D sign while still ledgible and containing all the required information has numerous bullet holes throughout.

Alternative Sediment Control. Observed silt fences and all were functional.

Revegetation. Observed cheatgrass areas. These are small isolated areas. The permittee has not performed any clipping nor was such a directive issued by the Division

Protection Of Environmental Values. The operator recently performed minor maintenance on runoff/erosion control. Some minor maintenance is suggested on several feber channels

Copy of report mailed to _____

Copy of report given to _____

Inspector's signature _____ No. _____

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. Act 015/017

Inspection Date 4/20/95

Please number comments to correspond with topics on previous page.

located on the reclaimed road outslope. Up to this point in time the fiber lined waterway and fiber dams have been effective in minimizing erosion.

Support Facilities. The lower and upper livestock control gap fences on Ivie Creek were in a good state of repair. No cattle signs, tracks etc were observed in the fenced reclaimed area.

Progress Report The following is a progress report on the joint work items identified in Carters letter to Mr Edmonson of 9/26/94:

Items 1, 2 & 3 / tabled see letter of 9/26/94

Items 5, 6, 7, 15, & 17 completed

Items 4, 8, 9, 10, 11, 12, 13, 14 & 16 - pending

Copy of report mailed to CalcMat / Lee Edmonson; OSM / Donna Griffin; DOGM / Joe Helfrich

Copy of report ~~given to~~ filed Price Field Office

Inspector's signature Tim J Gnalenick No. 26

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

4/26/95

DOGM/IR-2

an equal opportunity employer

11/86 001049