



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

INSPECTION REPORT

1594 West North Temple, Suite 1210
PO Box 145801
Salt Lake City, Utah 84114-5801
801-538-5340
801-359-3940 (Fax)
801-538-7223 (TDD)

Michael O. Leavitt
Governor
Lowell P. Braxton
Division Director

Partial:___ Complete: XXX Exploration:___
Inspection Date & Time: 6/3/99 / 10:00p.m.-4:00p.m.
Date of Last Inspection: 5/4/99

Mine Name: Hidden Valley Mine County: Emery Permit Number: ACT/015/007 #5
Permittee and/or Operator's Name: Consolidation Coal Company
Business Address: P.O. Box 566, Sesser, Illinois 62884
Type of Mining Activity: Underground XXX Surface___ Prep. Plant___ Other___
Company Official(s): None
State Officials(s): Bill Malencik, Sharon Falvey Federal Official(s): None
Weather Conditions: Cloudy, Raining
Existing Acreage: Permitted- 950 Disturbed- 7 Regraded-___ Seeded-___ Bonded- 7
Increased/Decreased: Permitted-___ Disturbed-___ Regraded-___ Seeded-___ Bonded-___
Status: Exploration/ XXX Active/___ Inactive/___ Temporary Cessation/___ Bond Forfeiture
Reclamation (Phase I/___ Phase II/___ Final Bond Release/___ Liability 1986 Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- Substantiate the elements on this inspection by checking the appropriate performance standard.
 - For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - For partial inspections check only the elements evaluated.
- Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	EVALUATED	N/A	COMMENTS	NOV/ENF
1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. SIGNS AND MARKERS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. TOPSOIL	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. HYDROLOGIC BALANCE:				
a. DIVERSIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
b. SEDIMENT PONDS AND IMPOUNDMENTS	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
c. OTHER SEDIMENT CONTROL MEASURES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
d. WATER MONITORING	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
e. EFFLUENT LIMITATIONS	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. EXPLOSIVES	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. NONCOAL WASTE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. SLIDES AND OTHER DAMAGE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. CONTEMPORANEOUS RECLAMATION	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. BACKFILLING AND GRADING	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
13. REVEGETATION	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. SUBSIDENCE CONTROL	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. CESSATION OF OPERATIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16. ROADS:				
a. CONSTRUCTION/MAINTENANCE/SURFACING	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
b. DRAINAGE CONTROLS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. OTHER TRANSPORTATION FACILITIES	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. SUPPORT FACILITIES/UTILITY INSTALLATIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
19. AVS CHECK (4th Quarter-April, May, June) <u>6/3/99</u> (date)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. AIR QUALITY PERMIT	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. BONDING & INSURANCE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
22. OTHER: ANNUAL REPORT	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

INSPECTION REPORT
(Continuation sheet)

Page 2 of 3

PERMIT NUMBER: ACT/015/007

DATE OF INSPECTION: 6/3/99

(Comments are Numbered to Correspond with Topics Listed Above)

GENERAL COMMENTS

A complete inspection of the Hidden Valley reclaimed mine site was conducted by the undersigned; Sharon Falvey. Mr. Behling was not available to participate on this inspection. The record inspection was completed in the morning.

SUMMARY

No violations were issued. The environmental control measures appear to meet the coal rule performance standards.

4A. HYDROLOGIC BALANCE: DIVERSIONS

The diversions were stable and showed no evidence of recent runoff. The diversion above the "A" seam maintained this past summer, meets performance standards. Some fine material from the escarpment is being deposited in the diversion, but doesn't constitute a concern at this point in time.

4D. HYDROLOGIC BALANCE: WATER MONITORING

The MRP requires water monitoring at high and low flow. The sampling on Ivie Creek above and below the mine are to be taken in May and September. The last sampling was taken September 21, 1998. The May sample has been taken. However, the lab results have not been received.

8. NONCOAL WASTE

The noncoal waste on the surface is not a problem. The exception is at the end of the county road. However, no noncoal waste, pop cans, etc. were observed during the instant inspection.

12. BACKFILLING AND GRADING

As previously documented in prior inspection reports, the "B" seam was regraded in 1997.

13. REVEGETATION

Seedlings we observed from last years rehabilitation efforts. The seedlings are most numerous in the regraded depression areas. See Susan White's technical report that is made an official part of the instant inspection.

INSPECTION REPORT
(Continuation sheet)

Page 3 of 3

PERMIT NUMBER: ACT/015/007

DATE OF INSPECTION: 6/3/99

(Comments are Numbered to Correspond with Topics Listed Above)

21. BONDING AND INSURANCE

Insurance expires 11/5/99. The surety bond is on records for \$90,758.00 and no bond release has been approved by the Division.

22. OTHER: ANNUAL REPORT

Annual report for 1997 was submitted to the Division on 3/26/98 and reviewed by the undersigned. Sharon Falvey stated she would contact Brian Butts, Consolidated Coal Company, on the reclamation plans for the balance of the area.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas, and Mining.

Copy of this Report:

Mailed to: Steve Behling/Tim Kirschbaum (Consol) Henry Austin (OSM)

Given to: Joe Helfrich (DOGM)

Filed to: Price Field Office

Date: June 10, 1999

Inspector's Signature: _____



Wm. J. Malencik

#26