



State of Utah
 DEPARTMENT OF NATURAL RESOURCES
 DIVISION OF OIL, GAS AND MINING

1594 West North Temple, Suite 1210
 PO Box 145801
 Salt Lake City, Utah 84114-5801
 (801) 538-5340 telephone
 (801) 359-3940 fax
 (801) 538-7223 TTY
 www.nr.utah.gov

Michael O. Leavitt
 Governor
 Robert L. Morgan
 Executive Director
 Lowell P. Braxton
 Division Director

10024

OK

INSPECTION REPORT

Partial XXX Complete ___ Exploration ___
 Inspection Date: 10/31/2002 / Time: 10:15a.m. to 2:00p.m.
 Date of Last Inspection: 09/24/2002

Mine Name: Hidden Valley Mine County: Emery Permit Number: C/015/007
 Permittee and/or Operator's Name: Consolidation Coal Company
 Business Address: P.O. Box 566, Sesser IL 62884/P.O. Box 527, Emery, Utah 84522
 Company Official(s): Steve Behling, Tim Kirschbaum Federal Official(s): None
 State Official(s): Joe Helfrich
 Weather Conditions: Sunny, 55
 Type of Mining Activity: Underground XXX Surface ___ Prep Plant ___ Other ___
 Existing Acreage: Permitted 960 Disturbed 7 Regraded ___ Seeded ___
 Status: Active

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	EVALUATED	N/A	COMMENTS	NOV/ENF
1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. SIGNS AND MARKERS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. TOPSOIL	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. HYDROLOGIC BALANCE:				
a. DIVERSIONS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
b. SEDIMENT PONDS AND IMPOUNDMENTS	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
c. OTHER SEDIMENT CONTROL MEASURES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
d. WATER MONITORING	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
e. EFFLUENT LIMITATIONS	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. EXPLOSIVES	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. NONCOAL WASTE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL ISSUES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. SLIDES AND OTHER DAMAGE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. CONTEMPORANEOUS RECLAMATION	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. BACKFILLING AND GRADING	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. REVEGETATION	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
14. SUBSIDENCE CONTROL	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. CESSATION OF OPERATIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16. ROADS:				
a. CONSTRUCTION/MAINTENANCE/SURFACING	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
b. DRAINAGE CONTROLS	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. OTHER TRANSPORTATION FACILITIES	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. SUPPORT FACILITIES/UTILITY INSTALLATIONS	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
19. AIR QUALITY PERMIT	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. AIR QUALITY PERMIT	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. BONDING & INSURANCE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Utah!

INSPECTION REPORT
(Continuation Sheet)

PERMIT NUMBER: C/015/007

DATE OF INSPECTION: 10/31/2002

(COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE)

1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE

The reclamation permit was renewed on January 29, 2002 and expires January 30, 2007. There are no amendments pending. The purpose of this site visit was to conduct a partial inspection of the reclaimed and associated disturbed areas.

2. SIGNS AND MARKERS

Point of access signs and perimeter markers were correctly posted.

4C. HYDROLOGIC BALANCE: OTHER SEDIMENT CONTROL MEASURES

The berms and ditches along the road, disturbed area, and reclaimed area were in good repair and functioning properly at the time of this inspection.

13. REVEGETATION

The shrubs, mat saltbush, fourwing saltbush, and shadscale were showing improved signs of vigor. Forbs and grasses were evident in the roughened areas. Ivie Creek was flowing at approximately 3 gallons per minute.

Inspector's Signature: _____


Joseph C. Helfrich #1

Date: November 1, 2002

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining.

cc: James Fulton, OSM
Tim Kirschbaum, Consol, Illinois
Seth McCourt, Consol, Emery
Price Field office

O:\015007.HID\Compliance\2002P_1031.doc