0014

Outgoing
C0150007
OK

From: Karl Houskeeper
To: IanMcClain@consolenergy.com; JohnGefferth@consolenergy.com ; SteveBehl...
CC: Angela Nance; Daron Haddock; Suzanne Steab
Date: 9/15/2009 10:19 AM
Subject: August 2009 Inspection Reports
Attachments: Emery August 2009.pdf; Hidden Valley August 2009.pdf

Attached are the August 2009 inspection reports for Emery Deep and Hidden Valley.

Karl

State of Utah

Department of Natural Resources

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA
Division Director

JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

Inspection Report

Representatives Present During the Inspection:		
Company	Ian McClain	Associate Engineer
OGM	Karl Houskeeper	Environmental Scientist III

Permit Number:	C0150007
Inspection Type:	PARTIAL
Inspection Date:	Tuesday, August 11, 2009
Start Date/Time:	8/11/2009 7:30:00 AM
End Date/Time:	8/11/2009 12:30:00 PM
Last Inspection:	Wednesday, July 15, 2009

Inspector: Karl Houskeeper, Environmental Scientist III

Weather: Clear, Temp. 82 Deg. F.

InspectionID Report Number: 2087

Accepted by: jhelfric
8/20/2009

Permitee: **CONSOLIDATION COAL CO**
Operator: **CONSOLIDATION COAL CO MID-CONTINENT REGION**
Site: **HIDDEN VALLEY MINE**
Address: **PO BOX 566, SESSER IL 62884**
County: **EMERY**
Permit Type: **PERMANENT COAL PROGRAM**
Permit Status: **RECLAIMED**

Current Acreages

960.00	Total Permitted
6.70	Total Disturbed
6.70	Phase I
	Phase II
	Phase III

Mineral Ownership

- ☐ Federal
- ☐ State
- ☐ County
- ☑ Fee
- ☐ Other

Types of Operations

- ☑ Underground
- ☐ Surface
- ☐ Loadout
- ☐ Processing
- ☐ Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Inspector's Signature: Karl R. Houskeeper **Date** Tuesday, August 11, 2009

Karl Houskeeper, Environmental Scientist III
Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

1594 West North Temple, Suite 1210, PO Box 145801, Salt Lake City, UT 84114-5801
telephone (801) 538-5340 • facsimile (801) 359-3940 • TTY (801) 538-7458 • *www.ogm.utah.gov*

Permit Number: C0150007
Inspection Type: PARTIAL
Inspection Date: Tuesday, August 11, 2009

Inspection Continuation Sheet

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

1. *Substantiate the elements on this inspection by checking the appropriate performance standard.*
   a. *For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.*
   b. *For PARTIAL inspections check only the elements evaluated.*
2. *Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.*
3. *Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.*
4. *Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.*

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	☐	☐	☐	☐
2. Signs and Markers	☑	☐	☑	☐
3. Topsoil	☐	☐	☐	☐
4.a Hydrologic Balance: Diversions	☑	☐	☑	☐
4.b Hydrologic Balance: Sediment Ponds and Impoundments	☑	☑	☐	☐
4.c Hydrologic Balance: Other Sediment Control Measures	☑	☐	☑	☐
4.d Hydrologic Balance: Water Monitoring	☐	☐	☐	☐
4.e Hydrologic Balance: Effluent Limitations	☑	☑	☐	☐
5. Explosives	☑	☑	☐	☐
6. Disposal of Excess Spoil, Fills, Benches	☑	☑	☐	☐
7. Coal Mine Waste, Refuse Piles, Impoundments	☑	☑	☐	☐
8. Noncoal Waste	☑	☐	☐	☐
9. Protection of Fish, Wildlife and Related Environmental Issues	☐	☐	☐	☐
10. Slides and Other Damage	☐	☐	☐	☐
11. Contemporaneous Reclamation	☐	☐	☐	☐
12. Backfilling And Grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence Control	☑	☑	☐	☐
15. Cessation of Operations	☐	☐	☐	☐
16.a Roads: Construction, Maintenance, Surfacing	☐	☐	☐	☐
16.b Roads: Drainage Controls	☐	☐	☐	☐
17. Other Transportation Facilities	☐	☐	☐	☐
18. Support Facilities, Utility Installations	☐	☐	☐	☐
19. AVS Check	☐	☐	☐	☐
20. Air Quality Permit	☑	☑	☐	☐
21. Bonding and Insurance	☐	☐	☐	☐
22. Other	☐	☐	☐	☐

2. Signs and Markers

The mine ID sign is in place and contains the required information.

4.a Hydrologic Balance: Diversions

Diversion along old reclaimed access road is functional.

4.c Hydrologic Balance: Other Sediment Control Measures

The silt fence adjacent to the mine ID sign is functional.