State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

GARY R. HERBERT
Governor

GREG BELL
Lieutenant Governor

Inspection Report

Permit Number:	**C0150007**
Inspection Type:	PARTIAL
Inspection Date:	Wednesday, October 22, 2014
Start Date/Time:	10/22/2014 8:30:00 AM
End Date/Time:	10/22/2014 2:00:00 PM
Last Inspection:	Wednesday, October 22, 2014

Inspector: Karl Houskeeper,

Weather: Partly Cloudy, Temp. 46 Deg. F.

InspectionID Report Number: 3999

Accepted by: JHELFRIC
10/29/2014

Representatives Present During the Inspection:	
Company	Russel Jensen
OGM	Karl Houskeeper

Permitee: **CONSOL MINING COMPANY, LLC**
Operator: **CONSOL MINING COMPANY, LLC**
Site: **HIDDEN VALLEY MINE**
Address: **1000 CONSOL ENERGY DRIVE, CANONSBURG PA 15317**
County: **EMERY**
Permit Type: **PERMANENT COAL PROGRAM**
Permit Status: **RECLAIMED**

Current Acreages

960.00	**Total Permitted**
6.70	**Total Disturbed**
6.70	**Phase I**
	Phase II
	Phase III

Mineral Ownership

- ☐ Federal
- ☐ State
- ☐ County
- ☑ Fee
- ☐ Other

Types of Operations

- ☑ Underground
- ☐ Surface
- ☐ Loadout
- ☐ Processing
- ☐ Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Karl R. Houskeeper

Inspector's Signature:

Karl Houskeeper,
Inspector ID Number: 49

Date Wednesday, October 22, 2014

Note: This inspection report does not constitute an official Order of compliance, with the regulatory program of the Division of Oil, Gas and Mining.

1594 West North Temple, Suite 1210, PO Box 145801, Salt Lake City, UT 84114-5801
telephone (801) 538-5340 • facsimile (801) 359-3940 • TTY (801) 538-7458 • www.ogm.utah.gov

UTAH DNR OIL, GAS & MINING

Permit Number: C0150007
Inspection Type: PARTIAL
Inspection Date: Wednesday, October 22, 2014

Inspection Continuation Sheet

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

1. *Substantiate the elements on this inspection by checking the appropriate performance standard.*
   a. *For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.*
   b. *For PARTIAL inspections check only the elements evaluated.*
2. *Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.*
3. *Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.*
4. *Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.*

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	☐	☐	☐	☐
2. Signs and Markers	☑	☐	☑	☐
3. Topsoil	☐	☐	☐	☐
4.a Hydrologic Balance: Diversions	☐	☐	☐	☐
4.b Hydrologic Balance: Sediment Ponds and Impoundments	☑	☑	☐	☐
4.c Hydrologic Balance: Other Sediment Control Measures	☑	☐	☑	☐
4.d Hydrologic Balance: Water Monitoring	☐	☐	☐	☐
4.e Hydrologic Balance: Effluent Limitations	☑	☑	☐	☐
5. Explosives	☑	☑	☐	☐
6. Disposal of Excess Spoil, Fills, Benches	☑	☑	☐	☐
7. Coal Mine Waste, Refuse Piles, Impoundments	☑	☑	☐	☐
8. Noncoal Waste	☑	☐	☑	☐
9. Protection of Fish, Wildlife and Related Environmental Issues	☐	☐	☐	☐
10. Slides and Other Damage	☐	☐	☐	☐
11. Contemporaneous Reclamation	☐	☐	☐	☐
12. Backfilling And Grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence Control	☐	☐	☐	☐
15. Cessation of Operations	☐	☐	☐	☐
16.a Roads: Construction, Maintenance, Surfacing	☐	☐	☐	☐
16.b Roads: Drainage Controls	☐	☐	☐	☐
17. Other Transportation Facilities	☐	☐	☐	☐
18. Support Facilities, Utility Installations	☐	☐	☐	☐
19. AVS Check	☐	☐	☐	☐
20. Air Quality Permit	☐	☐	☐	☐
21. Bonding and Insurance	☐	☐	☐	☐
22. Other	☐	☐	☐	☐

2. Signs and Markers

The mine identification is in place at the end of the county road and beginning of the mining permit area. The sign contains all of the required information.

4.c Hydrologic Balance: Other Sediment Control Measures

The only alternate sediment control on the site is a silt fence that is located adjacent to the mine identification sign . The silt fence was checked during the inspection and was found to be functional.

8. Noncoal Waste

The site was free of noncoal waste items.