State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

GARY R. HERBERT
Governor

GREG BELL
Lieutenant Governor

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Inspection Report

Permit Number:	**C0150007**
Inspection Type:	PARTIAL
Inspection Date:	Tuesday, April 12, 2016
Start Date/Time:	4/12/2016 9:30:00 AM
End Date/Time:	4/12/2016 3:00:00 PM
Last Inspection:	Wednesday, March 09, 2016

Representatives Present During the Inspection:	
Company	Kit Pappas
OGM	Karl Houskeeper

Inspector: Karl Houskeeper,

Weather: Clear Skies, Temp. 61 Deg. F.

InspectionID Report Number: 5496

Accepted by: JHELFRIC
4/18/2016

Permitee: **BRONCO UTAH OPERATIONS, LLC**
Operator: **BRONCO UTAH OPERATIONS, LLC**
Site: **HIDDEN VALLEY MINE**
Address: **PO BOX 527, EMERY UT 84522**
County: **EMERY**
Permit Type: **PERMANENT COAL PROGRAM**
Permit Status: **ACTIVE**

Current Acreages

960.00	**Total Permitted**
6.70	**Total Disturbed**
6.70	**Phase I**
	Phase II
	Phase III

Mineral Ownership

- ☐ **Federal**
- ☐ **State**
- ☐ **County**
- ☑ **Fee**
- ☐ **Other**

Types of Operations

- ☑ **Underground**
- ☐ **Surface**
- ☐ **Loadout**
- ☐ **Processing**
- ☐ **Reprocessing**

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Karl R. Houskeeper

Inspector's Signature:

Karl Houskeeper,
Inspector ID Number: 49

Date Tuesday, April 12, 2016

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

1594 West North Temple, Suite 1210, PO Box 145801, Salt Lake City, UT 84114-5801
telephone (801) 538-5340 • facsimile (801) 359-3940 • TTY (801) 538-7458 • *www.ogm.utah.gov*

UTAH DNR OIL, GAS & MINING

Permit Number: C0150007
Inspection Type: PARTIAL
Inspection Date: Tuesday, April 12, 2016

Inspection Continuation Sheet

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	☐	☐	☐	☐
2.	Signs and Markers	☑	☐	☑	☐
3.	Topsoil	☐	☐	☐	☐
4.a	Hydrologic Balance: Diversions	☑	☐	☑	☐
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	☑	☑	☐	☐
4.c	Hydrologic Balance: Other Sediment Control Measures	☑	☐	☑	☐
4.d	Hydrologic Balance: Water Monitoring	☐	☐	☐	☐
4.e	Hydrologic Balance: Effluent Limitations	☐	☐	☐	☐
5.	Explosives	☑	☑	☐	☐
6.	Disposal of Excess Spoil, Fills, Benches	☑	☑	☐	☐
7.	Coal Mine Waste, Refuse Piles, Impoundments	☑	☑	☐	☐
8.	Noncoal Waste	☐	☐	☐	☐
9.	Protection of Fish, Wildlife and Related Environmental Issues	☐	☐	☐	☐
10.	Slides and Other Damage	☐	☐	☐	☐
11.	Contemporaneous Reclamation	☐	☐	☐	☐
12.	Backfilling And Grading	☐	☐	☐	☐
13.	Revegetation	☐	☐	☐	☐
14.	Subsidence Control	☑	☑	☐	☐
15.	Cessation of Operations	☐	☐	☐	☐
16.a	Roads: Construction, Maintenance, Surfacing	☐	☐	☐	☐
16.b	Roads: Drainage Controls	☐	☐	☐	☐
17.	Other Transportation Facilities	☐	☐	☐	☐
18.	Support Facilities, Utility Installations	☐	☐	☐	☐
19.	AVS Check	☐	☐	☐	☐
20.	Air Quality Permit	☐	☐	☐	☐
21.	Bonding and Insurance	☐	☐	☐	☐
22.	Other	☐	☐	☐	☐

2. Signs and Markers

The mine identification sign is in place at the entrance into the mining permit area. A permit transfer has been requested and conditionally approved. A new mine identification sign is currently on order and will be installed upon approval of the transfer and receipt of the sign.

4.a Hydrologic Balance: Diversions

Diversion along side of the reclaimed access road is functional.

4.c Hydrologic Balance: Other Sediment Control Measures

Silt fence adjacent to the mine identification sign is functional.