



NO. N 85-6-13-1

notice of violation

To the following Permittee or Operator:

Name Trail Mountain Coal Company

Mine Trail Mountain Mine Surface Underground Other

County Emery State UTAH Telephone _____

Mailing Address P.O. Box 370 Orangeville UTAH 84537

State Permit No. ACT/OIS/009

Ownership Category State Federal Fee Mixed

Date of inspection Dec. 4, 1985, 19__

Time of inspection 10:00 a.m. p.m. to 12:15 a.m. p.m.

Operator Name (other than Permittee) _____

Mailing Address _____

Under authority of the Utah Coal Mining and Reclamation Act, Section 40-10-1 et seq., *Utah Code Annotated*, 1953, the undersigned authorized representative of the Division of Oil, Gas & Mining has conducted an inspection of above mine on above date and has found violation(s) of the act, regulations or required permit condition(s) listed in attachment(s). This notice constitutes a separate Notice of Violation for each violation listed.

You must abate each of these violations within the designated abatement time. You are responsible for doing all work in a safe and workmanlike manner.

The undersigned representative finds that **cessation of mining is** **is not** expressly or in practical effect required by this notice. For this purpose, "mining" means extracting coal from the earth or a waste pile, and transporting it within or from the mine site.

This notice shall remain in effect until it expires as provided on reverse side of this form, or is modified, terminated or vacated by written notice of an authorized representative of the director of the Division of Oil, Gas & Mining. Time for abatement may be extended by authorized representative for good cause, if a request is made within a reasonable time before the end of abatement period.

Date of service/mailling Dec 4, 1985

Time of service/mailling 12:00 a.m. p.m. Noon

Allen Childs
Permittee/Operator representative

Engineer
Title

[Signature]
Signature

Barton D. Kala
Division of Oil, Gas & Mining representative

Mining Field Specialist
Title

[Signature]
Signature

#6
Identification Number

SEE REVERSE SIDE

WHITE-DOG M YELLOW-OSM PINK-PERMITTEE/OPERATOR GOLDENROD-NOV FILE

DOG M 602



NOTICE OF VIOLATION NO. N 85-6-13-1

Violation No. 1 of 1

Nature of violation

Failure to pass disturbed area runoff through appropriate treatment facilities or a sediment pond before leaving the permit

Provisions of act, regulations or permit violated

UMC 817.42

Portion of operation to which notice applies

Lower Exit from the Loadout yard (Tipple area)

Remedial action required (including any interim steps)

Establish a defined swale and ditch arrangement to insure runoff does not leave the permit area

Abatement time (including interim steps)

4 working days - Dec 10, 1985