0001

UTAH NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. ACT/015/009

Inspection Date 12/4/86

Permittee/Operator Name Diamond Shamrock Coal Unit

Business Address P.O. Box 370

City Orangeville State UT Zip 84537-0370

Mine Trail Mountain Coal Company ☐ Surface ☒ Underground ☐ Other

County Emery State UT

Company Official(s) Allen Childs

State Official(s) Jim Fricke & Phil Ralphs (PR)

Time of inspection 1:30 ☐ a.m. ☒ p.m. to 4:00 ☐ a.m. ☒ p.m. ☒ Partial ☐ Complete

Date of last inspection 11/11/86 Weather conditions Fair & clear

Acreage ☒ Permitted 773.5 ☒ Disturbed 8.8 ☐ Regraded ☐ Seeded ☒ Bonded 8.8

Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☒	☐	☐	☒
2. Signs and markers	☒	☐	☐	☐
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
— Stream channel diversions	☐	☐	☐	☐
— Diversions	☒	☐	☐	☒
— Sediment ponds and impoundments	☒	☐	☐	☒
— Other sediment control measures	☐	☐	☐	☐
— Surface and groundwater monitoring	☐	☐	☐	☐
— Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☐	☐	☐	☐
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☐	☐	☐	☐

WHITE — DOGM YELLOW — OSM PINK — PERMITTEE/OPERATOR GOLDENROD — NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/009

Inspection Date 12/4/86

Please number comments to correspond with topics on previous page.

1. The operator is mining off tract, the Division granted an incidental boundary change on 11/19/86, WHICH COVERS PRESENT MINING AREA,

4. Sediment Ponds

The sediment pond contains a large amount of sediment, the operator is in the process of removing the sediment.

4. Diversions

The curb and gutter diversion on the east side of the mine yard is in good working order.

Copy of report mailed to Donna Griffin (OSM) & Allen Childs (TMM)

Copy of report given to Joe Helfrich, John Whitehead, Phil Ralphs

Inspector's signature Jim Tricke 12/16/86 No.

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE