9-22-88 0012

UTAH NATURAL RESOURCES
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • (801) 538-5340

inspection report

Permit No. ACT/015/009 7145
Inspection Date SEPT. 12, 1988

Permittee/Operator Name BEAVER CREEK COAL CO.
Business Address P.O. BOX 1378
City PRICE State UT Zip 84501
Mine TRAIL MOUNTAIN #9 ☐ Surface ☒ Underground ☐ Other
County EMERY State UT
Company Official(s) DAN GUY & PAUL KULBACK
State Official(s) BILL WAKEMACK
Time of inspection 9:30 ☒ a.m. ☐ p.m. to 11:00 ☒ a.m. ☐ p.m. ☒ Partial ☐ Complete
Date of last inspection AUG. 11, 1988 Weather conditions COOL & LIGHT RAIN
Acreage 415 ☒ Permitted 8.0 ☒ Disturbed ☐ Regraded ☐ Seeded 8.0 ☒ Bonded
Enforcement Action NONE

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. Permits	☐	☐	☐	☐
2. Signs and markers	☐	☐	☐	☐
3. Topsoil	☐	☐	☐	☐
4. Hydrologic balance				
a Stream channel diversions	☐	☐	☐	☐
b Diversions	☒	☐	☐	☒
c Sediment ponds and impoundments	☒	☐	☐	☒
d Other sediment control measures	☐	☐	☐	☐
e Surface and groundwater monitoring	☐	☐	☐	☐
f Effluent limitations	☐	☐	☐	☐
5. Explosives	☐	☐	☐	☐
6. Development waste and spoil disposal	☐	☐	☐	☐
7. Coal processing waste	☐	☐	☐	☐
8. Noncoal waste	☒	☐	☐	☒

	YES	NO	N/A	COMMENTS
9. Protection of fish, wildlife, and related environmental values	☐	☐	☐	☐
10. Slides and other damage	☐	☐	☐	☐
11. Contemporaneous reclamation	☐	☐	☐	☐
12. Backfilling and grading	☐	☐	☐	☐
13. Revegetation	☐	☐	☐	☐
14. Subsidence control	☐	☐	☐	☐
15. Cessation of operations	☐	☐	☐	☐
16. Roads				
— Construction	☐	☐	☐	☐
— Drainage controls	☐	☐	☐	☐
— Surfacing	☐	☐	☐	☐
— Maintenance	☐	☐	☐	☐
17. Other transportation facilities	☐	☐	☐	☐
18. Support facilities and utility installations	☒	☐	☐	☒

WHITE—DOGM YELLOW—OSM PINK—PERMITTEE/OPERATOR GOLDENROD—NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/009

Inspection Date SEPT. 12, 1988

Please number comments to correspond with topics on previous page.

GENERAL: DAN GUY & PAUL KULPACK (BEAVER CREEK) WERE ON HAND DURING THIS PARTIAL INSPECTION. A LIGHT RAIN WAS FALLING DURING THE DAY.

4b. DIVERSIONS

THE DIVERSION BEHIND THE OFFICE/BATHHOUSE WAS CLEANED & GRADED TO DRAIN. SOME ADDITIONAL MATERIAL NEAR THE SUBSTATION FENCE WILL BE REMOVED TO COMPLETE THE WORK.

4c. SEDIMENT PONDS & IMPOUNDMENTS

THE CONSTRUCTION OF THE SEDIMENT BASIN AT THE POND INLET WILL BE STARTED AFTER THE NON-COAL WASTE PADS HAVE SET. ALSO, CLEANING OF THE POND WILL COMMENCE AFTER CONSTRUCTION IS COMPLETED.

Copy of report mailed to

Copy of report given to

Inspector's signature BW #30 9/13/88 No.

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE

UTAH
NATURAL RESOURCES
Oil, Gas & Mining

INSPECTION REPORT COMMENTS

Permit No. ACT/015/009

Inspection Date SEPT 12, 1988

Please number comments to correspond with topics on previous page.

8. NON COAL WASTE

① THE RECENT STORM ACTIVITY HAS SCATTERED SOME GARBAGE FROM THE NON COAL WASTE STORAGE AREA & WILL BE CLEANED UP.

② PARS FOR THE NEW WASTE DUMPSTERS WERE BEING POURED DURING THIS INSPECTION & SHOULD BE READY WITHIN THE NEXT WEEK OR TWO. THIS AREA IS LOCATED JUST ABOVE THE SED POND & SHOULD ALLEVIATE SOME OF THE PRIOR GARBAGE PROBLEMS.

18. SUPPORT FACILITIES

DURING THIS INSPECTION, CREWS WERE INSTALLING NEW ENTRANCE GATES & FENCING.

Copy of report mailed to SLC FOR: BRIAN SMITH, OSM, JOE HELFRICH, DOGM; DAN GUY, BEAVER CREEK

Copy of report ~~given~~ FILED to PFO

Inspector's signature William A. Warnock 9/13/88 No. 30

WHITE – DOGM YELLOW – OSM PINK – PERMITTEE/OPERATOR GOLDENROD – NOV FILE