

7-27-89
7145

0022



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangerter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: July 5, 1989
.1 hour

Permittee and/or Operators Name: Beaver Creek Coal Company
Business Address: P O Box 1378 Price UT 84501
Mine Name: Trail Mountain Permit Number: ACT/015/009
Type of Mining Activity: Underground Surface Other
County: Emery
Company Official (s): _____
State Official(s): Joe Helfrich, Rade Orell, Tom Emmett
Partial: XX Complete: _____ Date of Last Inspection: May 10, 1989
Weather Conditions: Clear and Sunny
Acreage: Permitted _____ Disturbed _____ Regraded _____ Seeded _____ Bonded _____
Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

| | YES | NO | N/A | COMMENTS |
|--|-----|-----|-----|----------|
| 1. PERMITS | () | () | () | () |
| 2. SIGNS AND MARKERS | () | () | () | () |
| 3. TOPSOIL | () | () | () | () |
| 4. HYDROLOGIC BALANCE: | | | | |
| a. STREAM CHANNEL DIVERSIONS | () | () | () | () |
| b. DIVERSIONS | () | () | () | () |
| c. SEDIMENT PONDS AND IMPOUNDMENTS | () | () | () | () |
| d. OTHER SEDIMENT CONTROL MEASURES | () | () | () | () |
| e. SURFACE AND GROUNDWATER MONITORING | () | () | () | () |
| f. EFFLUENT LIMITATIONS | () | () | () | () |
| 5. EXPLOSIVES | () | () | () | () |
| 6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL | () | () | () | () |
| 7. COAL PROCESSING WASTE | () | () | () | () |
| 8. NONCOAL WASTE | () | () | () | () |
| 9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES | () | () | () | () |
| 10. SLIDES AND OTHER DAMAGE | () | () | () | () |
| 11. CONTEMPORANEOUS RECLAMATION | () | () | () | () |
| 12. BACKFILLING AND GRADING | () | () | () | () |
| 13. REVEGETATION | () | () | () | () |
| 14. SUBSIDENCE CONTROL | () | () | () | () |
| 15. CESSATION OF OPERATIONS | () | () | () | () |
| 16. ROADS | | | | |
| a. CONSTRUCTION | () | () | () | () |
| b. DRAINAGE CONTROLS | () | () | () | () |
| c. SURFACING | () | () | () | () |
| d. MAINTENANCE | () | () | () | () |
| 17. OTHER TRANSPORTATION FACILITIES | () | () | () | () |
| 18. SUPPORT FACILITIES | | | | |
| UTILITY INSTALLATIONS | () | () | () | () |

jb
MN85/11

INSPECTION REPORT
(continuation sheet)

DATE OF INSPECTION July 5, 1989

Page 2 of 2

On July 5, 1989, an aerial inspection of this site was conducted by the referenced State and Federal officials. No violations were observed.

Photographs (slides), were taken and are available at the Division of Oil, Gas and Mining, Salt Lake Office as well as the Office of Surface Mining, Albuquerque Field Office.

Copy of this Report:

Mailed/filed to: John Kathmann (OSM) Joe Helfrich (DOGM)
Filed to: PFO

Inspectors Signature Joe Helfrich  Date: July 27, 1989

jb
MN47/43