



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangerter
Governor

Dee C. Hansen
Executive Director

Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

*pgl
jcd*

INSPECTION REPORT

INSPECTION DATE & TIME: October 17, 1991
2:00 pm and 3:40 pm

Permittee and/or Operator's Name: Mountain Coal Company
Business Address: P. O. Box 1378, Price, UT 84501; (801) 637-5050
Mine Name: Trail Mountain #9 Permit Number: ACT/015/009
Type of Mining Activity: Underground Surface Other
County: Emery County Company Official(s): None
State Officials(s): Ken Wyatt
Federal Official(s): None
Partial: Complete Date of last Inspection: 09/12/91
Weather Conditions: clear, cool, slight breeze
Acreage: Permitted 1415 Disturbed 8.8 Regraded Seeded
Bonded 8.8
Enforcement Action: AVS check

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	(X)	()	()	(X)
2. SIGNS AND MARKERS	(X)	()	()	(X)
3. TOPSOIL	(X)	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	(X)	()	()	(X)
b. DIVERSIONS	(X)	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	(X)
d. OTHER SEDIMENT CONTROL MEASURES	()	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	(X)	()	()	(X)
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE & SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	()	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT

(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/009

DATE OF INSPECTION: 10/17/91

(Comments are Numbered to Correspond with Topics Listed Above)

1. PERMITS
Mountain Coal Company became the official permittee by Division letter dated September 19, 1991, with an effective date of September 13, 1991.
2. SIGNS AND MARKERS
The new permit identification signs have been ordered. Mr. Guy showed me a copy of the new signs that have been ordered. The only change from the old sign will be the permittee name and the Price, Utah mailing address. These signs will be posted as soon as they are received at the mine.
- 4a. HYDROLOGIC BALANCE: - STREAM CHANNEL DIVERSIONS
The inlets to the two undisturbed bypass culvert were clear and unobstructed. A small trickle was flowing in the creek above the mine.
- 4c. HYDROLOGIC BALANCE: - SEDIMENT PONDS AND IMPOUNDMENTS
The sediment pond was containing water. No discharge was occurring.
- 4f. HYDROLOGIC BALANCE: - EFFLUENT LIMITATIONS
No mine water was being discharged at this time.

Copies of this Report:

Mailed to: Bernie Freeman (OSM); Dan Guy (MCC)

Given to: Joe Helfrich (DOGM)

Inspector's Signature:  #42 Date: 10/28/91