



inspection report

- Partial
- Complete
- Exploration

Inspection Date: April 19, 1995
 Time: 8 : 00 am pm to 1 : 30 am pm
 Date of Last Inspection: 3/7/95

Mine Name: Trailbltn. County: Emery Permit Number: Act 015/009
 Permittee and/or Operator's Name: Pacy Corp/Energy West
 Business Address: P.O. Box 1005, Huntington, UT 84528
 Type of Mining Activity: Underground Surface Prep. Plant Other
 State Official(s): Bill Malencik
 Company Official(s): Karl Houkkeeper
 Federal Official(s): N/A

Weather Conditions: Clear/Windy
 Existing Acreage: Permitted-1450 Disturbed-24⁸ Regraded- Seeded- Bonded-24⁸
 Increased/Decreased: Permitted- Disturbed- Regraded- Seeded- Bonded-
 Status: Exploration / Active / Inactive / Temporary Cessation / Bond Forfeiture
 Reclamation (Phase I / Phase II / Final Bond Release / Liability Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	EVALUATED	N/A	COMMENTS	NOV/ENF
1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. SIGNS AND MARKERS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. TOPSOIL	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. HYDROLOGIC BALANCE:				
a. DIVERSIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
b. SEDIMENT PONDS AND IMPOUNDMENTS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
c. OTHER SEDIMENT CONTROL MEASURES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
d. WATER MONITORING	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
e. EFFLUENT LIMITATIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. EXPLOSIVES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. NONCOAL WASTE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. SLIDES AND OTHER DAMAGE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. CONTEMPORANEOUS RECLAMATION	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. BACKFILLING AND GRADING	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. REVEGETATION	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. SUBSIDENCE CONTROL	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
15. CESSATION OF OPERATIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16. ROADS:				
a. CONSTRUCTION/MAINTENANCE/SURFACING	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
b. DRAINAGE CONTROLS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. OTHER TRANSPORTATION FACILITIES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. SUPPORT FACILITIES/UTILITY INSTALLATIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
19. AVS CHECK (4th Quarter-April, May, June) <u>4/19/95</u> (date)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. AIR QUALITY PERMIT	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. BONDING & INSURANCE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

INSPECTION REPORT COMMENTS

Permit No. Act 015/009

Inspection Date 4/19/95

Please number comments to correspond with topics on previous page.

General Comments. A complete inspection was conducted and completed on 4/19/95. The permittee was represented by Karl Hoeskeeper.

The Trail altn mine is still undergoing reconstruction associated with the coal transportation intertie with the Cottonwood Mine. The long wall is scheduled to be moved from the Cottonwood Mine to the Trail Mtn Mine in August, 1995. The major project is the construction of the overhead beltline. The Division approved this project on both mines, Cottonwood and Trail Mtn.

Records. The following records were reviewed:

• Permits

- DOGM Mining and Reclamation permit approved for five years and expires 2/20/2000.
- UPDES permit on file and covers both the sediment pond and the mine water
- Insurance documents are on file
- Annual report was submitted to the Division on 4/19/95. The report included the subsidence data for C.Y 1994

Copy of report mailed to _____

Copy of report given to _____

Inspector's signature _____ No. _____

WHITE - DOGM YELLOW - OSM PINK - PERMITTEE/OPERATOR GOLDENROD - NOV FILE

INSPECTION REPORT COMMENTS

Permit No. Act 0151009

Inspection Date 4/19/95

Please number comments to correspond with topics on previous page.

- Public records concerning the Trail Mtn Mine are on file at the Emery County Court House. The records include the MRP and a letter to Emery County Recorder where other public records are available for review.
- Inspection Reports on Impoundments were reviewed:
 - ▲ Quarterly 3/29/95
 - ▲ Annual certified report dated 4/4/94.
- UPDES monthly reports were reviewed.
- Amendments
 - ▲ The most recent amendment approved by the Division concerns the overhead coal beltline between the Trail Mtn and the Cottonwood Mines.
 - ▲ The most recent amendment submitted to the Division concerns a proposal to integrate the Trail Mtn sewer system to the Cottonwood sewer system. The proposal is to pipe the Trail Mtn sewer to Cottonwood/Walberg. The pipeline as I understand the project will follow the underground mine beltline.
- Bond and reclamation agreement are on file.

Copy of report mailed to _____

Copy of report given to _____

Inspector's signature _____ No. _____

WHITE - DOGM YELLOW - OSM PINK - PERMITTEE/OPERATOR GOLDENROD - NOV FILE

INSPECTION REPORT COMMENTS

Permit No. Act 0151009

Inspection Date 4/19/95

Please number comments to correspond with topics on previous page.

- AVS information was reviewed
- Water monitoring was completed for the first quarter of C.V. 95 & was on file at the mine site
- Certified maps including designs are on file at the mine office.

Field

- Sediment pond contained runoff. Observed the inlets and outlet.
- Explosive storage area was observed. The area to store explosives is approved and has not changed as to location since the sale from Mtn. Coal to PacifiCorp. Appropriate signs were posted.
- Support facilities
 - ▲ The water treatment plant has been relocated as approved by the Division

Copy of report mailed to PC/Karl Houskeeper; OSM/Donna Quiffin; DOGM/Joe Helfrich

Copy of report given to Filed Price Field Office

Inspector's signature Tom J. Chalovich

No. 26

WHITE - DOGM YELLOW - OSM PINK - PERMITTEE/OPERATOR GOLDENROD - NOV FILE

4/24/95