

0006

From: Steve Demczak
To: Angela Nance; Guy Davis
Date: 7/15/2009 7:34 AM
Subject: June Insp
Attachments: 20090715074848.pdf

Outgoing
cf/015/0009
Q



State of Utah

Department of Natural Resources

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA
Division Director

JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

Representatives Present During the Inspection:	
Company	Guy Davis Environmental Scientist
OGM	Steve Demczak Environmental Scientist III

Inspection Report

Permit Number:	C0150009
Inspection Type:	COMPLETE
Inspection Date:	Thursday, June 11, 2009
Start Date/Time:	6/11/2009 10:00:00 PM
End Date/Time:	6/11/2009 2:00:00 PM
Last Inspection:	

Inspector: Steve Demczak, Environmental Scientist III

Weather: Cloudy 60's

InspectionID Report Number: 2038

Accepted by: jhelfric
7/9/2009

Permittee: **PACIFICORP**
 Operator: **ENERGY WEST MINING CO**
 Site: **TRAIL MOUNTAIN MINE**
 Address: **PO BOX 310, HUNTINGTON UT 84528**
 County: **EMERY**
 Permit Type: **PERMANENT COAL PROGRAM**
 Permit Status: **ACTIVE**

Current Acreages

3,538.98	Total Permitted
10.39	Total Disturbed
	Phase I
	Phase II
	Phase III

Mineral Ownership

- Federal
- State
- County
- Fee
- Other

Types of Operations

- Underground
- Surface
- Loadout
- Processing
- Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

No violations were issued. The Trail Mountain Mine remains in temporary cessation status; site conditions are unchanged. The permittee stated that they had clean diversion and built-up berms since the last inspection in March 2009.

Inspector's Signature:

Steve Demczak, Environmental Scientist III

Date

Tuesday, June 16, 2009

Inspector ID Number: 39

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

1594 West North Temple, Suite 1210, PO Box 145801, Salt Lake City, UT 84114-5801
telephone (801) 538-5340 • facsimile (801) 359-3940 • TTY (801) 538-7458 • www.ogm.utah.gov

Permit Number: C0150009
 Inspection Type: COMPLETE
 Inspection Date: Thursday, June 11, 2009

Inspection Continuation Sheet

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
19. AVS Check	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
22. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

1. Permits, Change, Transfer, Renewal, Sale

The current DOGM permit for Trail Mountain is undergoing a midterm review. Deficiencies were mailed to Energy West Mining Company on February 18, 2009.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

The sediment pond was inspected on March 25, 2009 for the first quarter of 2009. No hazardous conditions were reported. This pond did contain a small amount of water from the recent rain storms.

4.d Hydrologic Balance: Water Monitoring

The permittee will be submitting first quarter water monitoring to the Division by the end of the second quarter of 2009.

4.e Hydrologic Balance: Effluent Limitations

There has been no discharge from the sediment pond for the first quarter of 2009.

5. Explosives

There are no explosives at the site.

7. Coal Mine Waste, Refuse Piles, Impoundments

There are no refuse piles at this site.

8. Noncoal Waste

The site is mostly clean of non-coal waste material.

10. Slides and Other Damage

No slides or other damages was seen during the inspection.

13. Revegetation

The permittee has been requested to remove Tamarisk (Saltcedar) from the pad area of the mine site. This plant is on the State Noxious weed list. The permittee plans to cut down the plants.

14. Subsidence Control

The permittee has given subsidence information in the 2008 annual report.

15. Cessation of Operations

The mine is not active.

18. Support Facilities, Utility Installations

The support facilities have not changed since the last inspection.

Permit Number: C0150009
Inspection Type: COMPLETE
Inspection Date: Thursday, June 11, 2009

19. AVS Check

The midterm review of this permit has generated deficiencies relative to ownership and control information for the Energy West / PacifiCorp mine permits.

21. Bonding and Insurance

The insurance policy will expire on August 8, 2009. The bonding company is Assoc. Electric & Gas Ins. LTD. This policy meet the minimum requirements of the R645 Coal Rules.